

**APPENDIX 20**  
**STORM WATER RETENTION POND AND SOLAR EVAPORATION POND INSPECTION**  
**REPORTS**

**APPENDIX 20.1**  
**POND INSPECTION REPORTS**



Exide Technologies  
Frisco Recycling Center  
P.O. Box 250  
Frisco, TX 75034  
Tel (972) 335-2121

Certified Mail

November 09, 2011

Mr. Dan Siebeneicher  
TCEQ, Water Quality Division  
Storm Water & Pretreatment Team (MC-148)  
P.O. Box 13087  
Austin, TX 78711-3087

Re: Exide Technologies, FRC  
7471 South 5<sup>th</sup> Street, Frisco, TX  
TPDES Permit No. WQ0002964000  
Request for Storm Water Detention Pond Construction Verification

Mr. Siebeneicher:

The attached document is being provided per your request to W&M Environmental Group, Inc. (WM) on October 19, 2011. The storm water pond was constructed during 1988. Historical records, documentation and more recent surveying conducted by W&M were reviewed to provide you the requested information.

If you should require additional information please contact me at (225) 614-4977 or via email [edward.hardy@exide.com](mailto:edward.hardy@exide.com) or Mr. Frank Clark, P.E. of W&M Environmental, at (972) 509-9611.

Sincerely;

A handwritten signature in black ink, appearing to read "E. Hardy II", is written over a horizontal line.

Edward M. Hardy II  
Interim Environmental Manager  
Exide Technologies

Enclosure

cc: Frank Clark, W&M Environmental Group, Inc

November 9, 2011

Mr. Edward M. Hardy II  
Exide Technologies  
7471 South Fifth Street  
Frisco, Texas

RE: Storm Water Detention Pond Liner Specifications  
Exide Technologies  
7471 South Fifth Street  
Frisco, Texas  
TPDES Permit No. WQ0002964000 (TX0103292)  
W&M Project No. 112.034

Dear Mr. Hardy:

W&M Environmental Group, Inc. (W&M) performed surveying and soil liner characterization analysis to document the as-installed condition of the storm water detention pond located at the Exide Technologies (Exide) facility located at 7471 South Fifth Street in Frisco, Collin County, Texas (Site). The Site location is presented on **Figure 1**.

#### **STORM WATER POND SURVEYING ACTIVITIES**

W&M subcontracted Doug Connally and Associates, Inc. (DCA), a Texas Registered Professional Land Surveyor (RPLS), to perform the surveying activities around the detention pond. Surveying activities were conducted on July 17, 2008. DCA surveyed in the sides, slopes and bottom of the retention pond as well as the sump pump and influent pipe. The elevation survey conducted by DCA is presented on **Figure 2**. The elevation of the top of the storm water pond rim varies from 635.67 feet above mean sea level (MSL) in the northwest corner of the pond to 636.54 feet above MSL in the southwest corner of the pond. The surface area of the detention pond was determined to be 88,893 square feet or 2.04 acres.

W&M calculated the volume of the storm water pond to be 6,540,596 gallons based on the survey conducted by DCA. The capacity of the storm water pond to the top of the 3-foot diameter concrete pipe inlet (elevation 633.3 feet above MSL) was determined to be 4,570,721 gallons. The 8-foot wide by 16-foot long by 2.7 feet deep collection sump located in the middle of the pond has an additional capacity of 2,681 gallons.

#### **STORM WATER POND LINER EVALUATION**

W&M evaluated the storm water pond liner on September 19, 2008, to determine its compliance with the Texas Pollutant Discharge Elimination System Permit Number WQ002964000 (Permit) which states:

Mr. Edward Hardy  
November 9, 2011  
Page 2

*“Subsequent to this permit issuance date, all new wastewater or storm water ponds shall be lined in compliance with one of the following requirements:*

- a. Soil Liner: The soil liner should contain at least 3 feet of clay-rich (liquid limit greater than or equal to 30 and plasticity index greater than or equal to 15) soil material along the sides and bottom of the pond compacted in lifts of no more than 9 inches, to 95% standard proctor density at the optimum moisture content to achieve a permeability equal or less than  $1 \times 10^{-7}$  cm/sec.*
- b. Plastic/Rubber Liner: The liner shall be either a plastic or rubber membrane at least 30 mils in thickness which completely covers the sides and the bottom of the pond and which is not subject to degradation due to reaction with wastewater with which it comes into contact. If this lining material is vulnerable to ozone or ultraviolet deterioration it should be covered with a protective layer of soil of at least 6 inches. A leak detection system is also required.*
- c. Alternate Liner: The permittee shall submit plans for any other pond lining method. Pond liner plans must be approved in writing by the Executive Director of the Texas Commission on Environmental Quality prior to pond construction.”*

Exide provided W&M with a Texas Water Commission (TWC, predecessor to the TCEQ Water Quality Board) submittal dated June 2, 1987. The submittal was made by Lake Engineering on behalf of GNB Incorporated (now Exide). The submittal includes a “Concept Design Report” that specifies that the intended composition of the storm water detention pond was to be “double lined with 30 mil. PVC underliner and a 36 mil. overliner”. The original conceptual design did not include a leak detection system. It is presumed that GNB proposed the “double-lined” specifications to the TWC in order to meet a Criteria C (Alternate) liner. Response from the TWC has not been located but it is assumed that the specifications were agreed upon by GNB and the TWC.

W&M reviewed design drawings prepared by Lake Engineering & Development, Inc. (Lake Engineering) for the detention basin pond dated December 15, 1987, and issued as “As-Built” drawings in December 1988. The design called for two high-density polyethylene (HDPE) liners, each with a minimum thickness of 40 mils (0.040 inches), underlain by Geotextile fabrics and separated by a 6-inch sand layer. The native soils in the area are high plasticity clays, and it is believed the clays were compacted to form a soil liner below the two HDPE liners. A leak detection system was incorporated into the final design. The Lake Engineering drawings are presented in **Attachment A**.

Additionally, an As-built drawing created by Gundle dated August 13, 1988 indicates that the detention pond was constructed of two 40 mil. liners.

At some point in the early 1990’s, a severe storm event damaged the exposed pond liner system. According to Exide, a 60-mil liner was placed across the entire pond area at that time to replace the damaged portions and act as a more robust liner system.

W&M’s evaluation involved a review of the pond design and field documentation of the liner, drainage layer and underlying soil to verify the liner system satisfies the requirements of the permit. The field activities conducted in 2008 indicate that the overall condition of the liner was good and no evidence of photo-degradation was visible to the naked eye. Over the years, small punctures observed in the HDPE liner were repaired as they were identified by professional liner repair companies.

### **High-Density Polyethylene Liner Evaluation**

Three areas of the pond liner, designated SS-01 through SS-03, were evaluated to assess the location, thickness and condition of the HDPE membranes, and the density and physical characteristics of the

Mr. Edward Hardy  
November 9, 2011  
Page 3

underlying compacted soil. Sample locations are presented on **Figure 3**. During investigation of the pond liner system, it was observed that at least two layers of HDPE were overlaying the soil liner. The liner was cut using a box-cutter knife equipped with a hook-shaped blade. The uppermost liner was comprised of 60 mil HDPE and subsequent layers were determined to be 40 mil HDPE. The presence of the 60 mil liner directly above the 40 mil liner is consistent with the information provided by Exide regarding the repair of the entire liner system after a storm in the early 1990s. Both the 60 mil and 40 mil HDPE liners meet the required thickness of a plastic/rubber liner outlined in the TPDES permit. The HDPE liners located below the uppermost 60 mil liner are not believed to be exposed to the elements, ozone, or ultraviolet rays.

Two sections of the liner in the base of the pond were inspected corresponding to the locations of SS-01 and SS-03. In both instances, the uppermost HDPE liner layer was comprised of 60-mil HDPE. Underlying the 60-mil HDPE was a layer of 40-mil HDPE, underlain by a six to eight inch layer of fill sand. Underlying the layer of sand was a 40-mil HDPE layer lined with a geotextile liner. Beneath the final competent layer of HDPE in the area of SS-01 were two more layers of 40-mil HDPE; however, it is believed that these layers were overlap from the nearby seams. Underneath the HDPE liners was a clay liner. The clay liner was determined to be at least 2.5 feet thick in each of the three sampled areas. A photographic log is presented in **Attachment B** and a representative cross-section of the HDPE and clay liner for the areas around SS-01 and SS-03 are presented on **Figures 4 and 6**.

One section of the sidewall liner was inspected in the area corresponding to the location of SS-02. The uppermost layer of HDPE was also a 60 mil layer of HDPE directly underlain by geotextile liner underlain by a layer of 40-mil HDPE liner and another geotextile liner. Directly below the geotextile liner was the clay liner. The gray clay was dry and compacted. Small rock and gravel inclusions were documented. The gray clay transitioned into a lighter brown clay with depth. A representative cross section of the HDPE and clay liner around SS-02 is presented on **Figure 5**.

### Soil Liner Evaluation

Two surface soil samples, SS-01 and SS-03, were collected from the bottom of the detention pond. Once the layers of HDPE liner were removed from the area, W&M utilized a shovel and Shelby tube to collect representative samples of the clay liner. Approximately four two-gallon buckets and one Shelby tube was collected from each sampling area. The shelly tubes were advanced using a sledge hammer before any soil was disturbed with the shovel in order to collect an "intact" sample of the clay liner. A shovel was used to advance the opening to a depth of 2.5 feet to determine the thickness of the clay liner. The clay liner was at least 2.5 feet in thickness at each sampling location.

One surface soil sample, SS-02, was collected from the sidewall of the retention pond using methods similar to those used in the pond bottom. The sample was collected midway up the sidewall on the north side of the retention pond. The soil liner underlies two layers of HDPE liner and two layers of geotextile liner.

The recovered soil sample containers were sealed with a lid and the Shelby tubes were maintained in a horizontal position prior to delivery to Rone Engineering in Dallas, Texas, for geotechnical analyses including Standard Proctor Test, Atterberg Limits, lab permeability, unit weight, and percent passing through a #200 sieve.

Sampling locations were filled with bentonite chips to match grade and the HDPE liners were repaired by Lone Star Lining Company, an experienced liner installation and repair company, using extrusion welding methods with two layers of 40-mil HDPE liner.

Mr. Edward Hardy  
November 9, 2011  
Page 4

## Sample Analysis and Results

Geotechnical analytical results are summarized in **Table 1** and the laboratory analytical data package is presented in **Attachment C**. The geotechnical results indicate that the soils observed underlying the HDPE liner were sufficiently clayey to use as a clay liner. Each soil sample collected exceeded the Permit requirements for “clay-rich soil material” (liquid limit greater than or equal to 30 and a plasticity index greater than or equal to 15). However, Proctor testing and in-place density measurements on Shelby tube samples indicate the soils were not compacted to 95% of the Proctor density (values varied from 88.3% to 90.7% of maximum dry density). Laboratory permeability results also indicate that surface soil sample SS-02 satisfied the permeability requirements of a soil liner (permeability  $<1 \times 10^{-7}$  cm/sec), while surface soil samples SS-01 and SS-03 did not meet the soil liner requirements of the Permit.

## EVALUATION

The liner evaluation indicates that there are multiple artificial membranes, varying in thickness from 40 mils to 60 mils, overlying a clay layer at least 2.5 feet in thickness.

Physical testing on the clay liner in three representative locations indicates that, although the soil has satisfactory physical properties to meet the Permit requirements, it may not have been compacted adequately. As a result, the clay liner alone does not satisfy the Permit requirements for density or permeability that would apply to a clay liner system.

Because the detention pond was designed and installed with redundant liners consisting of at least two artificial membranes in addition to the clay soil, W&M evaluated this as an alternate liner system as allowed in the Permit. The HDPE membrane liners, if installed alone, each exceed the required 30 mil thickness outlined in the Permit. The composite liner system was evaluated using the procedures developed by Giroud & Bonaparte<sup>1</sup>, which consider the nature of the clay liner, the estimated number and size of defects in the artificial liner, the head of liquid on the liner system, and the contact between the liner and clay layer.

To simplify the evaluation, it was assumed that a single HDPE membrane is present above the clay soil liner, and the detention basin was nearly full, with approximately 10 feet of standing water on the liner system. In actuality, the basin is typically not full, and the second HDPE liner was not considered in the calculations.

The analysis was completed assuming approximately two defects per acre, with sizes of 0.1 square centimeter each ( $0.1 \text{ cm}^2$ ), a typical value for liners installed under supervision, and  $1.0 \text{ cm}^2$  each, a conservative value indicative of more frequent or larger imperfections.

---

<sup>1</sup> Giroud, J.P. and Bonaparte, R., 1989, “Leakage Through Liners Constructed with Geomembranes - Parts I and II”, *Geotextiles and Geomembranes*.

Mr. Edward Hardy  
November 9, 2011  
Page 5

| CONDITION                                                                       | DESIGN CRITERIA                                                                                                         | DESIGN UNIT<br>LEAKAGE RATE<br>(gpd/ft <sup>2</sup> ) |
|---------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| TCEQ Design Criteria                                                            | 3' clay<br>$k=1 \times 10^{-7}$ cm/sec                                                                                  | 0.009                                                 |
| Exide Clay Soil Liner<br>Only                                                   | 3' clay<br>Average permeability ( $k=25 \times 10^{-7}$ cm/sec)<br>Lowest permeability ( $k=7.3 \times 10^{-6}$ cm/sec) | 0.228*<br>0.640*                                      |
| Exide Soil Liner<br>System (Clay Liner<br>with one artificial<br>HDPE membrane) | 3' clay<br>Average permeability ( $k=25 \times 10^{-7}$ cm/sec)                                                         | 0.0005                                                |
|                                                                                 | Average defects (two 0.1 cm <sup>2</sup> defects per acre)                                                              | 0.0006                                                |
|                                                                                 | 3' clay<br>Lowest permeability ( $k=7.3 \times 10^{-6}$ cm/sec)                                                         | 0.0012                                                |
|                                                                                 | Average defects (two 0.1 cm <sup>2</sup> defects per acre)                                                              | 0.0015                                                |

\*value exceeds unit design leakage rate in Permit

The evaluation indicates that the clay/HDPE liner system satisfies the Permit requirements, with estimated leakage rates within the design criteria. The analysis is conservative because the second HDPE liner and the drainage layer were not considered; both features would further reduce the volume of water that would seep through the basin under assumed conditions.

Mr. Edward Hardy  
November 9, 2011  
Page 6

## CONCLUSIONS

DCA performed surveying activities to determine the dimensions and capacity of the storm water detention pond located on the Exide facility located at 7471 South Fifth Street in Frisco, Texas. Based upon the DCA drawings, the capacity of the storm water retention pond was determined to be 6,540,596 gallons. The capacity of the storm water detention pond from the bottom of the pond to the top of the inlet pipe was determined to be 4,570,721 gallons.

The storm water detention pond is lined with at least two layers of HDPE liner separated by fill sand. The top layer of the HDPE liner was determined to be 60 mils thick and the lower layers were determined to be 40 mils thick. Underlying the HDPE liners is a compacted clay soil liner at least 2.5 feet thick. Three samples were collected from the clay liner and submitted for geotechnical analysis to determine the physical properties and permeability of the soil liner. The physical testing indicates that, although the soil has satisfactory physical properties to meet the permit requirements, it may not have been compacted adequately, and as a result, does not satisfy the permit requirements for density or permeability that would apply to a clay liner system.

Because the detention pond was designed and installed with redundant HDPE membrane liners in addition to the clay soil, W&M evaluated this as an alternate liner system using industry-established procedures. The evaluation, using reasonable and conservative input parameters, indicates that the clay/HDPE liner system satisfies the Permit requirements, with estimated leakage rates within the design criteria.

W&M appreciates the opportunity to be of service to you on this project. If you have any questions or need additional information, please feel free to contact us.


Very truly yours,


W&M ENVIRONMENTAL GROUP, INC.

W&M ENVIRONMENTAL GROUP, INC.


Nick Foreman  
Environmental Scientist II

Frank W. Clark, P.E., P.G.  
Senior Consultant






## LEGEND



**Figure 2**  
**Storm Water Pond Liner**  
**Elevation Survey**  
7471 South Fifth Street  
Frisco, Texas






LEGEND  
Sample Location

0' 25' 50'  
APPROXIMATE SCALE

Figure 3  
Storm Water Pond Liner  
Sample Locations  
7471 South Fifth Street  
Frisco, Texas






LEGEND

Sand
 Clay
 60 mil HDPE Liner
 40 mil HDPE Liner
 Geotextile Liner

Figure 4  
 Storm Water Pond Liner  
 Cross-Section - SS-01  
 7471 South Fifth Street  
 Frisco, Texas





LEGEND

Clay

60 mil HDPE Liner

40 mil HDPE Liner

Geotextile Liner

Figure 5  
Storm Water Pond Liner  
Cross-Section - SS-02  
7471 South Fifth Street  
Frisco, Texas







Figure 6  
Storm Water Pond Liner  
Cross-Section - SS-03  
7471 South Fifth Street  
Frisco, Texas



**TABLE 1**  
**SOIL LINER GEOTECHNICAL DATA SUMMARY TABLE**

**Exide Technologies**  
**Frisco, TX**

| Sample ID <sup>1</sup> | Date Collected | Max Dry Density <sup>2</sup> | Optimum Moisture Content <sup>2</sup> | Liquid Limit <sup>2</sup> | Plastic Limit <sup>2</sup> | Plasticity Index <sup>2</sup> | Passing #200 <sup>2</sup> | Dry Unit Weight <sup>2</sup> | Moisture Content <sup>2</sup> | Permeability <sup>2</sup> |
|------------------------|----------------|------------------------------|---------------------------------------|---------------------------|----------------------------|-------------------------------|---------------------------|------------------------------|-------------------------------|---------------------------|
|                        |                | (pcf) <sup>3</sup>           | (%)                                   | (Unitless)                | (Unitless)                 | (Unitless)                    | (%)                       | (pcf)                        | (%)                           | (cm/sec)                  |
| SS-01 (Bulk)           | 9/19/08        | 97.0                         | 21.4                                  | 65.0                      | 23.0                       | 42.0                          | 71.3                      | -                            | -                             | -                         |
| SS-01 (0'-1')          | 9/19/08        | -                            | -                                     | -                         | -                          | 47                            | -                         | 84.4                         | 28.3                          | -                         |
| SS-01 (1'-2')          | 9/19/08        | -                            | -                                     | -                         | -                          | -                             | -                         | 87.8                         | 32.8                          | 1.4*10 <sup>-07</sup>     |
| SS-02 (Bulk)           | 9/19/08        | 101.4                        | 21.6                                  | 63.0                      | 22.0                       | 41.0                          | 77.5                      | -                            | -                             | -                         |
| SS-02 (0'-1')          | 9/19/08        | -                            | -                                     | -                         | -                          | 49                            | -                         | 107.7                        | 22.2                          | -                         |
| SS-02 (1'-2')          | 9/19/08        | -                            | -                                     | -                         | -                          | -                             | -                         | 92.0                         | 29.2                          | 1.7*10 <sup>-08</sup>     |
| SS-03 (Bulk)           | 9/19/08        | 91.5                         | 26.0                                  | 72.0                      | 26.0                       | 46.0                          | 74.5                      | -                            | -                             | -                         |
| SS-03 (0'-1')          | 9/19/08        | -                            | -                                     | -                         | -                          | 53                            | -                         | 84.5                         | 29.1                          | -                         |
| SS-03 (1'-2')          | 9/19/08        | -                            | -                                     | -                         | -                          | -                             | -                         | 80.8                         | 35.5                          | 7.3*10 <sup>-06</sup>     |

**Notes:**

<sup>1</sup>Samples collected on September 19, 2008 were collected by W&M Environmental Group, Inc, and analyzed by Rone Engineering.


<sup>2</sup>Geotechnical analysis performed in accordance with ASTM D-4318 and ASTM-D-698 Method-A.

<sup>3</sup>pcf - pounds per cubic foot

(-) - not applicable

**LAKE ENGINEERING  
DRAWINGS**

**ATTACHMENT A**





**PHOTOGRAPHIC LOG**

**ATTACHMENT B**




**Photo 1: Exide facility storm water detention pond on the morning of September 19, 2009. Photo taken facing north-west.**



**Photo 2: Second layer of HDPE liner (40 mil) revealed after the top HDPE liner (60 mil) was removed in the area of soil sample SS-01 located in the southeast corner of the pond.**



**Attachment B**  
**Photographic Log**  
7471 South Fifth Street  
Frisco, Texas



**Photo 3: Photograph depicting the layers of lining at surface soil sample SS-01. Six-inches of fill sand underlying the top two layer of HDPE and underlain by a 40 mil HDPE layer, a geotextile layer, and two more HDPE layers.**



**Photo 4: Shelby tube advanced to a depth of two feet to collect SS-01. Four two-gallon buckets and a shelly tube were collected at each soil sample**



**Attachment B**  
**Photographic Log**  
 7471 South Fifth Street  
 Frisco, Texas



**Photo 5: Photograph depicting the layers of lining at surface soil sample SS-02 located on the north sidewall. A layer of 60 mil HDPE lining underlain by a geotextile fabric, underlain by a 40 mil liner, underlain by a geotextile fabric, underlain by a clay liner.**



**Photo 6: Shelby tube advanced to a depth of 1.5 feet to collect SS-02. This sample location was advanced to a depth of 2.5 feet into the clay soil liner.**



**Attachment B**  
**Photographic Log**  
 7471 South Fifth Street  
 Frisco, Texas



**Photo 7: Photograph depicting a 60 mil HDPE layer underlain by a 40 mil layer, underlain by an 8 inch layer of fill sand, underlain by another 40 mil HDPE layer.**



**Photo 8: Plugging the open holes in the pond liner with bentonite chips prior to covering it with fill sand and sealing it with two layers of 40 mil HDPE using extrusion welding methods.**



**Attachment B**  
**Photographic Log**  
 7471 South Fifth Street  
 Frisco, Texas



**Photo 9: Photograph depicting a new layer of 40 mil HDPE installed on the east end of the storm water detention pond and the pond liner repair crew repairing the liner at soil sample SS-03.**



**Photo 10: North sidewall of pond showing repair of the liner breached to collect soil sample SS-02.**



**Attachment B**  
**Photographic Log**  
7471 South Fifth Street  
Frisco, Texas

07-31-09

Pond Liner Inspection

W&M Project No.: 112.034

**LABORATORY  
ANALYTICAL DATA**

**ATTACHMENT C**



8908 Ambassador Row, Dallas, TX 75247  
 7701 W Little York, Ste 600, Houston, TX 77040  
 4421 Freidrich, Ste 195, Austin, TX 78744  
 Corporate Phone: (214) 630-9745

## Report of Moisture Density Relationship

**Client:** W&M Environmental Group, Inc.  
 906 E. 18th Street  
 Plano, TX 75074

**Report No.:** 334208  
**Project No.:** 0814889  
**Date of Service:** 09/25/2008  
**Report Date:** 10/08/2008

**Project:** W & M Enviromental Services  
 Dallas, TX.

**Services:** Obtain a sample of material from the jobsite, bring the sample back to the laboratory and perform a moisture density relationship test in accordance with ASTM Standards.

### PROJECT DATA

**Contractor:**  
**Test For:** Storm Water Pond (Bulk Sample)  
**Material:** Dark Brown Fat Clay with Sand  
**Classification:** Storm Water Pond (Bulk Sample)  
**Test Method:** ASTM D-4318  
 ASTM D-698 Method-A


**Date Sampled:** 09/25/2008  
**Material Preparation:** Dry  
**Rammer Type:** Mechanical  
**Sampled By:** Cox, Debera  
**Sample Location:**  
 Exide SS-01

### REPORT OF TEST

Maximum Dry Density, pcf: 97.0  
 Optimum Moisture Content, %: 21.4

**Liquid Limit:** 65  
**Plastic Limit:** 23  
**Plasticity Index:** 42

**% Passing #200:** 71.3



**Technician:** Debera Cox

**Report Distribution:**

Charge: W&M Environmental Group, Inc. Attn: Mr. Nick Foreman  
 Orig: W&M Environmental Group, Inc. (Plano, TX)  
 Attn: Mr. Nick Foreman (1-ec copy)  
 1-ec Rone Project Manager Attn: Mr. K. Scott Watson AET

**Rone Engineering**

K. Scott Watson, AET  
 Project Manager



8908 Ambassador Row, Dallas, TX 75247  
 7701 W Little York, Ste 600, Houston, TX 77040  
 4421 Freidrich, Ste 195, Austin, TX 78744  
 Corporate Phone: (214) 630-9745

## Report of Moisture Density Relationship

**Client:** W&M Environmental Group, Inc.  
 906 E. 18th Street  
 Plano, TX 75074

**Report No.:** 334209  
**Project No.:** 0814889  
**Date of Service:** 09/25/2008  
**Report Date:** 10/08/2008

**Project:** W & M Enviromental Services  
 Dallas, TX.

**Services:** Obtain a sample of material from the jobsite, bring the sample back to the laboratory and perform a moisture density relationship test in accordance with ASTM Standards.

### PROJECT DATA

**Contractor:**  
**Test For:** Storm Water Pond (Bulk Sample)  
**Material:** Dark Brown & Tan Fat Claywith Sand & Trace Gravel  
**Classification:** Storm Water Pond (Bulk Sample)  
**Test Method:** ASTM D-4318  
 ASTM D-698 Method-B


**Date Sampled:** 09/25/2008  
**Material Preparation:** Dry  
**Rammer Type:** Mechanical  
**Sampled By:** Cox, Debera  
**Sample Location:**  
 Exide SS-02

### REPORT OF TEST

Maximum Dry Density, pcf: 101.4  
 Optimum Moisture Content, %: 21.6

**Liquid Limit:** 63  
**Plastic Limit:** 22  
**Plasticity Index:** 41

**% Passing #200:** 77.5



**Technician:** Debera Cox

**Report Distribution:**

Charge: W&M Environmental Group, Inc. Attn: Mr. Nick Foreman  
 Orig: W&M Environmental Group, Inc. (Plano, TX)  
 Attn: Mr. Nick Foreman (1-ec copy)  
 1-ec Rone Project Manager Attn: Mr. K. Scott Watson AET

**Rone Engineering**

K. Scott Watson, AET  
 Project Manager



8908 Ambassador Row, Dallas, TX 75247  
 7701 W Little York, Ste 600, Houston, TX 77040  
 4421 Freidrich, Ste 195, Austin, TX 78744  
 Corporate Phone: (214) 630-9745

## Report of Moisture Density Relationship

**Client:** W&M Environmental Group, Inc.  
 906 E. 18th Street  
 Plano, TX 75074

**Report No.:** 334210  
**Project No.:** 0814889  
**Date of Service:** 09/25/2008  
**Report Date:** 10/08/2008

**Project:** W & M Enviromental Services  
 Dallas, TX.

**Services:** Obtain a sample of material from the jobsite, bring the sample back to the laboratory and perform a moisture density relationship test in accordance with ASTM Standards.

### PROJECT DATA

**Contractor:**  
**Test For:** Storm Water Pond (Bulk Sample)  
**Material:** Dark Brown Fat Clay with Sand  
**Classification:** Storm Water Pond (Bulk Sample)  
**Test Method:** ASTM D-4318  
 ASTM D-698 Method-A


**Date Sampled:** 09/25/2008  
**Material Preparation:** Dry  
**Rammer Type:** Mechanical  
**Sampled By:** Cox, Debera  
**Sample Location:**  
 Exide SS-03

### REPORT OF TEST

Maximum Dry Density, pcf: 91.5  
 Optimum Moisture Content, %: 26.0

**Liquid Limit:** 72  
**Plastic Limit:** 26  
**Plasticity Index:** 46

**% Passing #200:** 74.5



**Technician:** Debera Cox

**Report Distribution:**

Charge: W&M Environmental Group, Inc. Attn: Mr. Nick Foreman  
 Orig: W&M Environmental Group, Inc. (Plano, TX)  
 Attn: Mr. Nick Foreman (1-ec copy)  
 1-ec Rone Project Manager Attn: Mr. K. Scott Watson AET

**Rone Engineering**

K. Scott Watson, AET  
 Project Manager



8908 Ambassador Row, Dallas, TX 75247  
7701 W Little York, Ste 600, Houston, TX 77040  
4421 Freidrich, Ste 195, Austin, TX 78744  
Corporate Phone: (214) 630-9745

## Report of Permeability Testing

**Client:** W&M Environmental Group, Inc.  
906 E. 18th Street  
Plano, TX 75074

**Report No.:** 334208A  
**Project No.:** 0814889  
**Date of Service:** 09/25/2008  
**Report Date:** 11/25/2008

**Project:** W & M Enviromental Services  
Dallas, TX.

**Services:** Permeability Testing

### Report of Tests

On this date, a Rone Engineering Services, Ltd. representative(s) received shelby tube soil samples for laboratory testing. The results are given below.

Sample ID: SS01 EXIDE (Shelby Tube 0' - 1')  
Material Description: Dark Brown Clay with Iron Ore  
Plasticity Index: 47  
Percent Passing No. 200 Sieve: 90.01%  
Moisture Content: 28.3%  
Dry Unit Weight: 84.4 pcf

Sample ID: SS02 EXIDE (Shelby Tube 0' - 1')  
Material Description: Dark Brown Clay with Trace Gravel  
Plasticity Index: 49  
Percent Passing No. 200 Sieve: 89.22%  
Moisture Content: 22.2%  
Dry Unit Weight: 107.7 pcf

Sample ID: SS03 EXIDE (Shelby Tube 0' - 1')  
Material Description: Dark Brown Clay  
Plasticity Index: 53  
Percent Passing No. 200 Sieve: 98.79%  
Moisture Content: 29.1%  
Dry Unit Weight: 84.5 pcf

## Report of Permeability Testing

**Client:** W&M Environmental Group, Inc.  
906 E. 18th Street  
Plano, TX 75074

**Report No.:** 334208A  
**Project No.:** 0814889  
**Date of Service:** 09/25/2008  
**Report Date:** 11/25/2008

**Project:** W & M Enviromental Services  
Dallas, TX.

**Services:** Permeability Testing

## Report of Tests

Sample ID: SS01 EXIDE (Shelby Tube 1' - 2')  
Material Description: Dark Brown Clay with Iron Ore  
Moisture Content: 32.8%  
Dry Unit Weight: 87.8 pcf  
Permeability: 1.4E-07 cm/sec

Sample ID: SS02 EXIDE (Shelby Tube 1' - 2')  
Material Description: Dark Brown Clay with Trace Gravel  
Moisture Content: 29.2%  
Dry Unit Weight: 92.0 pcf  
Permeability: 1.7E-08 cm/sec

Sample ID: SS03 EXIDE (Shelby Tube 1' - 2')  
Material Description: Dark Brown Clay  
Moisture Content: 35.5%  
Dry Unit Weight: 80.8 pcf  
Permeability: 7.3E-06 cm/sec

**Technician:** Debera Cox

**Report Distribution:**


Charge: W&M Environmental Group, Inc. Attn: Mr. Nick Foreman

Orig: W&M Environmental Group, Inc. (Plano, TX)

Attn: Mr. Nick Foreman (1-ec copy)

1-ec Rone Project Manager Attn: Mr. K. Scott Watson AET

**Rone Engineering**



K. Scott Watson, AET  
Project Manager

**APPENDIX 20.2**  
**LINER INSPECTION REPORT**



## MEMORANDUM

---

|              |                                                                                                                                     |                     |                        |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------|---------------------|------------------------|
| <b>Date:</b> | March 20, 2014                                                                                                                      | <b>Project No.:</b> | 130-2086               |
| <b>To:</b>   | Matt Love                                                                                                                           | <b>Company:</b>     | Exide Technologies     |
| <b>From:</b> | David E. Poe, P.E., Jay Winters, P.G.                                                                                               |                     |                        |
| <b>cc:</b>   |                                                                                                                                     | <b>Email:</b>       | Jay_Winters@golder.com |
| <b>RE:</b>   | <b>INSPECTION OF LINER SYSTEMS FOR THE STORMWATER RETENTION POND AND SOLAR EVAPORATION POND – EXIDE TECHNOLOGIES, FRISCO, TEXAS</b> |                     |                        |

---

### 1.0 INTRODUCTION

Golder Associates Inc. (Golder) has prepared this memorandum summarizing the field inspections of the Stormwater Retention Pond (SWRP) and the Solar Evaporation Pond (SEP) at the Exide facility in Frisco, Texas. David Poe, P.E., of Golder performed the field inspections in December 2013. The following report summarizes the field inspection findings.

Review of the report titled “Stormwater Detention Pond Liner Specifications”, as prepared by W&M Environmental Group, Inc. (November 9, 2011), indicates that the SWRP was constructed in 1988 and originally was comprised of two 40-mil high density polyethylene liners, underlain by a geotextile fabrics and separated by a 6-inch thick sand drainage layer (pg. 2). The report further states that at some point in the early 1990’s, a severe storm damaged and exposed the pond liner system, and a 60-mil HDPE liner was placed over the pond (pg. 2).

Both the SWRP and SEP appear to have been lined with 60 mil HDPE liner.

### 1.1 Scope of Inspections

The inspections were limited to visual observations of the membrane liners from the top of the pond slopes. The lower portions of the sideslopes and the bottom of the ponds could not be observed as the ponds currently impound water. The depth of impounded water was not determined during the field observations.

The perimeters of the ponds were traversed twice, slowly, as the liner was visually inspected. Photographs of the pond liners were taken from various perspectives along the perimeters of the ponds, and are attached as Exhibit A.

## 2.0 STORMWATER RETENTION POND (SWRP) INSPECTION

### 2.1 BACKGROUND

The SWRP is a membrane-lined pond with approximate dimensions of 300 feet and 125 feet (west and east slopes, respectively) by approximately 450 feet (north and south slopes), and an approximate area of



## MEMORANDUM

2.2 acres. The SWRP is located near the southwest corner of the Exide property, immediately north of the Crystallization Unit.

The liner system is comprised of fusion-welded high density polyethylene (HDPE) membrane. The liner material appears to be 60 mil in thickness (approximately 0.06 inches). Observations indicate the liner was originally welded using double fusion welding (for seams) and extrusion welding (for patches at sample locations and repairs). The HDPE is black in color, indicating that it was manufactured with carbon black, which facilitates the liner being exposed to ultraviolet sunlight without damage.

The pond appears to have been constructed with 1.5H:1V or steeper interior slopes. The liner is anchored around the perimeter in what appears to be a concrete-filled anchor trench.

Photographs (PHOTOS 1 through 8) of the SWRP are included in the attached Exhibit A.

## 2.2 INSPECTION FINDINGS

### 2.2.1 *Observations of Liner Condition and Maintenance*

Overall, the liner was observed to be in excellent condition. A few minor abrasions were observed in the liner material, as well as several surficial gouges or indentations. However, no liner penetrations below the crest of the pond liner and above the waterline were observed. Welding (both fusion and extrusion welds) appear to be consistent with industry standards. No excessive displacement, folds, fishmouths, shoving, or excessive movement were observed in the liner or underlying liner foundation. The inlet culvert liner appeared intact and in excellent condition. The bands securing the liner to the inlet culvert appeared to be in good condition and functioning as designed. Overall, the liner condition is assessed to be excellent.

### 2.2.2 *Observed Liner Defects*

Two defects were observed in the liner material, although neither exists below the crest elevation of the liner, and can be addressed in the future as maintenance items.

The first defect is located near the southeast corner of the pond, in the anchor trench. A perforation appears to have been caused by maintenance or vegetation removal from the anchor trench. The perforation is at a location beyond the pond crest, and does not represent an environmental risk or a risk to the stability of the pond liner.

The second defect appears to be a cut in the HDPE liner that may be a remnant from the original liner installation. As shown on Photo 6, a cut immediately adjacent to a fusion-welded patch exists in the northwest corner of the pond. The cut appears to be approximately 6 inches in length, and is located



## MEMORANDUM

immediately adjacent to a fusion weld on the patch. The patch is located beyond the crest of the pond liner, and does not represent an environmental risk or a risk to the stability of the pond liner.

### **2.2.3 Anchor Trench Observations**

As shown in a number of photographs, a separation has opened between the liner and the concrete backfill believed to have originally been placed within the anchor trench around the perimeter of the pond liner. Vegetation was observed to have become established at several locations between the liner and the concrete, although it is apparent the vegetation has now been cut and removed. Root systems were observed still existing in the opening between the liner and concrete.

Golder understands that the SWRP will be decommissioned over the next several years as a component of ongoing remediation being performed at the site. The opening between the concrete and liner does not appear to pose any short-term environmental risk or structural risk to the pond liner or slopes, and can remain in its current state until decommissioning. In the event future plans call for maintaining the pond indefinitely, then repairs might include backfilling the opening with concrete or compacted sand. Removal and replacement of the existing concrete backfill is not recommended, as potential damage to the liner or foundation soils is possible.

### **2.2.4 Perimeter Fencing**

As shown in the attached photographs, the perimeter fencing at the SWRP is intact and appears to be well maintained.

### **2.2.5 Additional Observations**

#### Sacrificial Rub Sheets or Other Protective Covering over Metal Pipe and Hose Fixtures

Golder observed one hose with a metal connector lying on the top of the HDPE liner. Golder recommends that metal fixtures or connectors be wrapped in a plastic sacrificial sheet or other measures to eliminate direct contact of metal fixtures or connectors onto the HDPE liner. While no damage was observed on the liner from the metal connector, using rub sheets or other protective measures over the liner represents good practices for protection of membrane liner systems.

## **3.0 SOLAR EVAPORATION POND (SEP) INSPECTION**

### **3.1 BACKGROUND**

The SEP is a membrane-lined pond with approximate dimensions of 150 feet by approximately 260 feet, and an approximate area of 0.9 acres. The SEP is located near the northwest corner of the Exide property, immediately southwest of the Class 2 Landfill.



## MEMORANDUM

The liner system is comprised of fusion-welded high density polyethylene (HDPE) membrane. The liner material appears to be 60 mil in thickness (approximately 0.06 inches). Observations indicate the liner was originally welded using double fusion welding (for seams) and extrusion welding (for patches at sample locations and repairs). The HDPE is black in color, indicating that it was manufactured with carbon black, which facilitates the liner being exposed to ultraviolet sunlight without damage.

The pond appears to have been constructed with 2H:1V or steeper interior slopes. The liner is anchored around the perimeter in what appears to be a concrete filled anchor trench.

Photographs (PHOTOS 9 through 15) of the SEP are included in the attached Exhibit A.

### 3.2 INSPECTION FINDINGS

#### 3.2.1 *Observations of Liner Condition and Maintenance*

Overall, the liner was observed to be in excellent condition. A few minor abrasions were observed in the liner material. However, no liner penetrations below the crest of the pond liner and above the waterline were observed. Welding (both fusion and extrusion welds) appear to be consistent with industry standards. No excessive displacement, folds, fishmouths, shoving, or excessive movement were observed in the liner or underlying liner foundation. The inlet culvert liner appeared intact and in excellent condition. The bands securing the liner to the inlet culvert appeared to be in good condition and functioning as designed. Overall, the liner condition is assessed to be excellent.

#### 3.2.2 *Observed Liner Defects*

A single defect/damage was observed in the liner material, although the liner damage exists above the crest elevation of the liner, and can be addressed in the future as a maintenance item.

The defect is located at the southeast corner of the pond, immediately adjacent to the anchor trench. The liner appears to have been torn, potentially by maintenance equipment (see PHOTO 14). The tear is at a location beyond the pond crest, and does not represent an environmental risk or a risk to the stability of the pond liner.

#### 3.2.3 *Anchor Trench Observations*

The liner appears to be anchored in a soil trench. Vegetation is well established over the anchor trench, and the liner appears to be secure within the anchor.

#### 3.2.4 *Perimeter Fencing*

As shown in the attached photographs, the perimeter fencing at the SEP is intact and appears to be well maintained. No action required.



## MEMORANDUM

### 3.2.5 Additional Observations

#### Sacrificial Rub Sheets or Other Protective Covering over Metal Pipe and Hose Fixtures

Golder observed several hoses with metal connectors lying on the top of the HDPE liner. Golder recommends that metal fixtures or connectors be wrapped in a plastic sacrificial sheet or other measures to eliminate direct contact of metal fixtures or connectors onto the HDPE liner. While no damage was observed on the liner from the metal connector, using rub sheets or other protective measures over the liner represents good practices for protection of membrane liner systems.

### 4.0 LIMITATIONS

Golder's inspection was limited to visual inspection of the pond liners above the waterline, as observed from the crest of the lined pond slopes. Due to the steepness of the pond sideslopes, traversing the slopes as a component of the inspection was not possible. The integrity or soundness of the welds (both fusion and extrusion) at the ponds were not evaluated for this inspection. Golder's conclusion that the pond liners appear to be in excellent condition is based on the described visual observations only.

### EXHIBITS

A - Photographs

**Project Title: Stormwater Retention Pond (SWRP)****PHOTO 1 - SWRP**

Looking West.

**PHOTO 2 - SWRP**

Eastern Slope of Pond with Inlet.





March 2014

2

130-2086

**PHOTO 3 - SWRP**

Southern Slope of Pond.


**PHOTO 4 - SWRP**

Pond Inlet on Eastern Slope.



**PHOTO 5 - SWRP**

Northern Slope of Pond

**PHOTO 6 - SWRP**

Cut in Liner at Patch (located above Crest of Pond Liner at Northwest Corner of Pond). Note damage (6-in cut) at toe of boot, along extrusion weld.



**PHOTO 7 - SWRP**

Separation of Concrete  
Anchor Trench Fill and  
Liner at Southern Slope of  
Pond

**PHOTO 8 - SWRP**

Separation of Concrete  
Anchor Trench Fill and  
Liner at Northern Slope of  
Pond



**Project Title: Solar Evaporation Pond (SEP)****PHOTO 9 - SEP**

Looking Northwest from  
Southeast Corner.

**PHOTO 10 - SEP**

Southern Slope of Pond.





March 2014

6

130-2086

**PHOTO 11 - SEP**

Western Slope of Pond.

**PHOTO 12 - SEP**

Northern Slope of Pond.





March 2014

7

130-2086

**PHOTO 13 - SEP**

Eastern Slope of Pond.

**PHOTO 14 - SEP**

Liner Damage in Southeast Corner of Pond (Note: Damage Located at Elevation above Eastern Crest of Pond).



**PHOTO 15 - SEP**

Transfer Pump Station.



**APPENDIX 21**  
**DOCUMENTATION FROM FORMER FRC PERSONNEL REGARDING FILL MATERIAL**  
**BELOW THE BATTERY RECEIVING/STORAGE BUILDING**

---

**AFFIDAVIT OF BILLY J. KING**

---

STATE OF TEXAS       §  
                                  §  
COUNTY OF COLLINS   §

BEFORE ME, the undersigned authority, on this day personally appeared Billy J. King, known to me to be the person whose name is ascribed below who being by me first duly sworn, upon his oath, stated as follows:


1.     My name is Billy J. King. I am over the age of 21 years and have never been convicted of a crime. I am under no disability, and I am fully competent to make this affidavit. I have personal knowledge of the facts stated here, and they are true and correct.
2.     I am currently employed by Exide Technologies ("Exide") as Director of Technologies, a corporate position.
3.     From August of 1983 until the present, I have been employed by the owners of the Frisco Battery Recycling Center located at 7471 South Fifth Street in Frisco, Collin County, Texas, including Exide and GNB Technologies, Inc.
4.     From August 1983 to the present, my positions were based at, and I was regularly present at, the Frisco Battery Recycling Center.
5.     In my positions as Quality Control Manager, Environmental and Quality Control Manager, Production Manager, Division Metallurgist, Technical Services Manager, Corporate Metallurgist, and Director of Technologies held during these time frames, I was involved in or familiar with the site conditions and waste management and disposal practices at the Frisco Battery Recycling Center.

6. When I began working at the Frisco Battery Recycling Center in August 1983, I became familiar with the Frisco Battery Recycling Center site conditions and past on-site disposal practices.
7. From August 1983 to the present and, to the best of my knowledge from at least November 16, 1980 forward, hazardous waste was not disposed of or otherwise used as fill on-site, other than in the instances of treatment failure associated with waste deposited in the on-site Class 2 Landfill.
8. Further, for clarity, no hazardous waste was used as fill when the Battery Receiving/Storage Building was constructed in the late 1980s.
9. I conveyed this information in a telephone call with Ms. Aileen Hooks in May 2013 for use in development of the Affected Property Assessment Report for the Frisco Battery Recycling Center.

FURTHER AFFIANT sayeth not.

Billy J. King  
Affiant


21<sup>st</sup> SUBSCRIBED AND SWORN to before me by Billy J. King on this day of February, 2014, to which witness my hand and seal of office.



Brooke R. Vanaman  
Notary Public in and for the State of Texas

My Commission Expires: 2.19.17

**APPENDIX 22**  
**HISTORICAL AERIAL PHOTOGRAPHS**



INQUIRY #: 3280329.1

YEAR: 1951

| = 500'





INQUIRY #: 3280329.1

YEAR: 1956

| = 500'






INQUIRY #: 3280329.1

YEAR: 1968

| = 500'





INQUIRY #: 3280329.1

YEAR: 1972

| = 500'





INQUIRY #: 3280329.1

YEAR: 1984

| = 500'





INQUIRY #: 3280329.1

YEAR: 1995

| = 500'





INQUIRY #: 3280329.1

YEAR: 2004

| = 500'





INQUIRY #: 3280329.1

YEAR: 2005

| = 500'





INQUIRY #: 3280329.1

YEAR: 2006

| = 500'





INQUIRY #: 3280329.1

YEAR: 2008

— = 500'



**APPENDIX 23**  
**FRC FEED DOCUMENTATION**

**Table A23-1**  
**2011 Feed Materials**  
**Frisco Recycling Center**  
**Frisco, Texas**

| Description of Feed Material  | Weight (lbs.)      | Overall Percentage of Feed Material |
|-------------------------------|--------------------|-------------------------------------|
| Scrap junk batteries          | 627,718,280        | 88.27%                              |
| Industrial plates             | 17,414,916         | 2.45%                               |
| Reverb slag                   | 16,180,560         | 2.28%                               |
| Remelt lead/ingot             | 10,407,857         | 1.46%                               |
| Scrap oxide wet               | 9,565,285          | 1.35%                               |
| Scrap plates & separators     | 4,021,011          | 0.57%                               |
| Industrial cells/ D           | 3,991,684          | 0.56%                               |
| Pot dross                     | 3,766,945          | 0.53%                               |
| Scrap acid tank sump          | 3,625,269          | 0.51%                               |
| Gel cell plastic batteries    | 2,753,386          | 0.39%                               |
| Industrial batteries          | 2,394,622          | 0.34%                               |
| Scrap lead                    | 1,639,791          | 0.23%                               |
| Scrap pasted grids            | 1,574,896          | 0.22%                               |
| Wheel weights                 | 1,535,492          | 0.22%                               |
| Baghouse dust                 | 891,582            | 0.13%                               |
| Battery tops/top lead         | 721,216            | 0.10%                               |
| Scrap dross                   | 671,024            | 0.09%                               |
| Scrap oxide dry               | 549,425            | 0.08%                               |
| Industrial cells/ W           | 545,396            | 0.08%                               |
| Telephone batteries           | 413,760            | 0.06%                               |
| Golf cart batteries           | 256,042            | 0.04%                               |
| Scrap junks drained           | 237,052            | 0.03%                               |
| Scrap lead shot               | 143,169            | 0.02%                               |
| Antimonial skim               | 40,980             | 0.01%                               |
| Floor sweepings               | 28,720             | 0.00%                               |
| Expanded metal punch          | 11,386             | 0.00%                               |
| Miscellaneous non-auto lead-A | 10,040             | 0.00%                               |
| Scrap cable strips/ S         | 9,790              | 0.00%                               |
| Scrap plates dry              | 9,412              | 0.00%                               |
| Scrap lead anodes             | 3,420              | 0.00%                               |
| <b>TOTAL</b>                  | <b>711,132,408</b> | <b>1</b>                            |

Notes:

1. Information provided by Exide February 13, 2013.



# MATERIAL SAFETY DATA SHEET

| I. PRODUCT IDENTIFICATION                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                |                                                      |                                       |                           |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------|---------------------------------------|---------------------------|-------|
| <b>MANUFACTURER</b><br>Exide Technologies<br>13000 Deerfield Parkway, Bldg. 200<br>Milton, GA 30004                                                                                                                                                                                                                                                                                                                                 |                                                                                                                | <b>CHEMICAL/TRADE NAME</b><br>(as used on label)     |                                       | Lead-Acid Battery         |       |
| <b>FOR INFORMATION</b><br>Primary: MACTEC Engineering and Consulting, Inc.<br>Telephone: (770) 421-3485<br>Secondary: Environmental, Safety & Health<br>Attention: Eric Murray (800) 523-4622<br>Fred Ganster (610) 921-4052                                                                                                                                                                                                        |                                                                                                                | <b>CHEMICAL FAMILY/CLASSIFICATION</b>                |                                       | Electric Storage Battery  |       |
| <b>FOR EMERGENCY</b><br>CHEMTREC (800) 424-9300<br>24-hour Emergency Response Contact<br>Ask for Environmental Coordinator                                                                                                                                                                                                                                                                                                          |                                                                                                                | <b>DATE ISSUED:</b>                                  |                                       | February 1, 2011          |       |
|                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                                |                                                      |                                       | Page 1 of 5               |       |
|                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                                | CHEMTREC INTERNATIONAL (703) 527-3887 – Collect      |                                       |                           |       |
| II. HAZARDOUS INGREDIENTS/IDENTITY INFORMATION                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                                |                                                      |                                       |                           |       |
|                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                                | Approximate Air Exposure Limits (µg/m <sup>3</sup> ) |                                       |                           |       |
| Components                                                                                                                                                                                                                                                                                                                                                                                                                          | CAS Number                                                                                                     | % by Wt.                                             | OSHA                                  | ACGIH                     | NIOSH |
| Inorganic compounds of:                                                                                                                                                                                                                                                                                                                                                                                                             |                                                                                                                |                                                      |                                       |                           |       |
| Lead                                                                                                                                                                                                                                                                                                                                                                                                                                | 7439-92-1                                                                                                      | 54-62                                                | 50                                    | 50                        | 50    |
| Antimony                                                                                                                                                                                                                                                                                                                                                                                                                            | 7440-36-0                                                                                                      | 0.4                                                  | 500                                   | 500                       | 500   |
| Tin                                                                                                                                                                                                                                                                                                                                                                                                                                 | 7440-31-5                                                                                                      | 0.16                                                 | 2000                                  | 2000                      | 2000  |
| Calcium                                                                                                                                                                                                                                                                                                                                                                                                                             | 7440-70-2                                                                                                      | 0.02                                                 | -                                     | -                         | -     |
| Arsenic                                                                                                                                                                                                                                                                                                                                                                                                                             | 7440-38-2                                                                                                      | 0.01                                                 | 10                                    | 10                        | 2     |
| Electrolyte (sulfuric acid/water/solution)                                                                                                                                                                                                                                                                                                                                                                                          | 7664-93-9                                                                                                      | 26-40                                                | 1000                                  | 200                       | 1000  |
| Case Material:                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                                |                                                      |                                       |                           |       |
| Polypropylene                                                                                                                                                                                                                                                                                                                                                                                                                       | 9003-07-0                                                                                                      | 5-12                                                 | N/A                                   | N/A                       | N/A   |
| Hard Rubber                                                                                                                                                                                                                                                                                                                                                                                                                         | --                                                                                                             |                                                      |                                       |                           |       |
| Plate separator material:                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                |                                                      |                                       |                           |       |
| Polyethylene                                                                                                                                                                                                                                                                                                                                                                                                                        | 9002-88-4                                                                                                      | 1-2                                                  | N/A                                   | N/A                       | N/A   |
| NOTE: Inorganic lead and electrolyte (water and sulfuric acid solution) are the primary components of every battery manufactured by Exide Technologies or its subsidiaries. Other ingredients may be present dependent upon battery type. Polypropylene is the principal case material of automotive and commercial batteries.                                                                                                      |                                                                                                                |                                                      |                                       |                           |       |
| III. PHYSICAL DATA - ELECTROLYTE                                                                                                                                                                                                                                                                                                                                                                                                    |                                                                                                                |                                                      |                                       |                           |       |
| Boiling Point                                                                                                                                                                                                                                                                                                                                                                                                                       | 203° F-240° F (for S.G. range)                                                                                 |                                                      | Specific Gravity (H <sub>2</sub> O=1) | 1.230 to 1.350            |       |
| Melting Point                                                                                                                                                                                                                                                                                                                                                                                                                       | Not Applicable                                                                                                 |                                                      | Vapor Pressure (mm Hg) 77° F          | 17 to 11 (for S.G. range) |       |
| Solubility in Water                                                                                                                                                                                                                                                                                                                                                                                                                 | 100%                                                                                                           |                                                      | Vapor Density (AIR=1)                 | Greater than 1            |       |
| Evaporation Rate (Butyl acetate=1)                                                                                                                                                                                                                                                                                                                                                                                                  | Less Than 1                                                                                                    |                                                      | % Volatiles by Weight                 | Not Applicable            |       |
| Appearance and Odor                                                                                                                                                                                                                                                                                                                                                                                                                 | A clear liquid with a sharp, penetrating, pungent odor. A battery is a manufactured article; no apparent odor. |                                                      |                                       |                           |       |
| IV. FIRE AND EXPLOSION HAZARD DATA                                                                                                                                                                                                                                                                                                                                                                                                  |                                                                                                                |                                                      |                                       |                           |       |
| Flash Point:                                                                                                                                                                                                                                                                                                                                                                                                                        | Not Applicable                                                                                                 |                                                      |                                       |                           |       |
| Flammable Limits:                                                                                                                                                                                                                                                                                                                                                                                                                   | LEL = 4.1% (Hydrogen Gas in air) ; UEL = 74.2%                                                                 |                                                      |                                       |                           |       |
| Extinguishing media:                                                                                                                                                                                                                                                                                                                                                                                                                | CO <sub>2</sub> ; foam; dry chemical                                                                           |                                                      |                                       |                           |       |
| <b>Special Fire Fighting Procedures:</b> Use positive pressure, self-contained breathing apparatus. Beware of acid splatter during water application and wear acid-resistant clothing, gloves, face and eye protection. If batteries are on charge, shut off power to the charging equipment, but, note that strings of series connected batteries may still pose risk of electric shock even when charging equipment is shut down. |                                                                                                                |                                                      |                                       |                           |       |

**IV. FIRE AND EXPLOSION HAZARD DATA (CONTINUED)**

**Unusual Fire and Explosion Hazards:** In operation, batteries generate and release flammable hydrogen gas. They must always be assumed to contain this gas which, if ignited by burning cigarette, naked flame or spark, may cause battery explosion with dispersion of casing fragments and corrosive liquid electrolyte. Carefully follow manufacturer's instructions for installation and service. Keep away all sources of gas ignition and do not allow metallic articles to simultaneously contact the negative and positive terminals of a battery.

**V. REACTIVITY DATA**

**Stability:** Stable   X    
Unstable       

**Conditions to Avoid:** Prolonged overcharge at high current; sources of ignition.

**Incompatibility: (materials to avoid)**

Electrolyte: Contact with combustibles and organic materials may cause fire and explosion. Also reacts violently with strong reducing agents, metals, sulfur trioxide gas, strong oxidizers, and water. Contact with metals may produce toxic sulfur dioxide fumes and may release flammable hydrogen gas.

Lead compounds: Avoid contact with strong acids, bases, halides, halogenates, potassium nitrate, permanganate, peroxides, nascent hydrogen, and reducing agents.

**Hazardous Decomposition Products:**

Electrolyte: Sulfur trioxide, carbon monoxide, sulfuric acid mist, sulfur dioxide, hydrogen sulfide.

Lead compounds: Temperatures above the melting point are likely to produce toxic metal fume, vapor, or dust; contact with strong acid or base or presence of nascent hydrogen may generate highly toxic arsine gas.

**VI. HEALTH HAZARD DATA****Routes of Entry:**

Electrolyte: Harmful by all routes of entry.

Lead compounds: Hazardous exposure can occur only when product is heated above the melting point, oxidized or otherwise processed or damaged to create dust, vapor, or fume.

**Inhalation:**

Electrolyte: Breathing of sulfuric acid vapors or mists may cause severe respiratory irritation.

Lead compounds: Inhalation of lead dust or fumes may cause irritation of upper respiratory tract and lungs.

**Ingestion:**

Electrolyte: May cause severe irritation of mouth, throat, esophagus, and stomach.

Lead compounds: Acute ingestion may cause abdominal pain, nausea, vomiting, diarrhea, and severe cramping. This may lead rapidly to systemic toxicity.

**Skin Contact:**

Electrolyte: Severe irritation, burns, and ulceration.

Lead compounds: Not absorbed through the skin.

**Eye Contact:**

Electrolyte: Severe irritation, burns, cornea damage, blindness.

Lead compounds: May cause eye irritation.

**Effects of Overexposure - Acute:**

Electrolyte: Severe skin irritation, damage to cornea may cause blindness, upper respiratory irritation.

Lead compounds: Symptoms of toxicity include headache, fatigue, abdominal pain, loss of appetite, muscular aches and weakness, sleep disturbances, and irritability.

**Effects of Overexposure - Chronic:**

Electrolyte: Possible erosion of tooth enamel; inflammation of nose, throat, and bronchial tubes.

**VI. HEALTH HAZARD DATA (CONTINUED)**

Lead compounds: Anemia; neuropathy, particularly of the motor nerves, with wrist drop; kidney damage; reproductive changes in both males and females.

**Carcinogenicity:**

Electrolyte: The National Toxicology Program (NTP) and the International Agency for Research on Cancer (IARC) have classified "strong inorganic acid mist containing sulfuric acid" as a substance that is carcinogenic to humans. This classification does not apply to sulfuric acid solutions in static liquid state or to electrolyte in batteries. Batteries subjected to abusive charging at excessively high currents for prolonged periods of time without vent caps in place may create a surrounding atmosphere of the offensive strong inorganic acid mist containing sulfuric acid.

Lead compounds: Listed as a 2B carcinogen, likely in animals at extreme doses. Proof of carcinogenicity in humans is lacking at present.

Arsenic: Listed by International Agency for Research on Cancer (IARC), OSHA and NIOSH as a carcinogen only after prolonged exposure at high levels.

**Medical Conditions Generally Aggravated by Exposure:**

Overexposure to sulfuric acid mist may cause lung damage and aggravate pulmonary conditions. Contact of electrolyte (water and sulfuric acid solution) with skin may aggravate skin diseases such as eczema and contact dermatitis. Contact of electrolyte (water and sulfuric acid solution) with eyes may damage cornea and/or cause blindness. Lead and its compounds can aggravate some forms of kidney, liver, and neurologic diseases.

**Emergency and First Aid Procedures**

**Inhalation:** Electrolyte: Remove to fresh air immediately. If breathing is difficult, give oxygen.

Lead compounds: Remove from exposure, gargle, wash nose and lips; consult physician.

**Ingestion:** Electrolyte: Give large quantities of water; **do not** induce vomiting; consult physician.

Lead compounds: Consult physician immediately.

**Skin:** Electrolyte: Flush with large amounts of water for at least 15 minutes; remove contaminated clothing completely, including shoes.

Lead compounds: Wash immediately with soap and water.

**Eyes:** Electrolyte and Lead compounds: Flush immediately with large amounts of water for at least 15 minutes; consult physician immediately.

**VII. PRECAUTIONS FOR SAFE HANDLING AND USE****Handling and Storage:**

Store batteries under roof in cool, dry, well-ventilated areas that are separated from incompatible materials and from activities that may create flames, spark, or heat. Store on smooth, impervious surfaces that are provided with measures for liquid containment in the event of electrolyte spills. Keep away from metallic objects that could bridge the terminals on a battery and create a dangerous short-circuit. Handle carefully and avoid tipping, which may allow electrolyte leakage. Single batteries pose no risk of electric shock but there may be increasing risk of electric shock from strings of connected batteries exceeding three 12-volt units.

**Charging:**

There is a possible risk of electric shock from charging equipment and from strings of series connected batteries, whether or not being charged. Shut-off power to chargers whenever not in use and before detachment of any circuit connections. Batteries being charged will generate and release flammable hydrogen gas. Charging space should be ventilated. Keep battery vent caps in position. Prohibit smoking and avoid creation of flames and sparks nearby. Wear face and eye protection when near batteries being charged.

**Spill or Leak Procedures:**

Stop flow of material, contain/absorb small spills with dry sand, earth, and vermiculite. Do not use combustible materials. If possible, carefully neutralize spilled electrolyte with soda ash, sodium bicarbonate, lime, etc. Wear acid-resistant clothing, boots, gloves, and face shield. **Do not allow discharge of un-neutralized acid to sewer.** Neutralized acid must be managed in accordance with approved local, state, and federal requirements. Consult state environmental agency and/or federal EPA.

**Waste Disposal Methods:**

Spent batteries: Send to secondary lead smelter for recycling.

**VII. PRECAUTIONS FOR SAFE HANDLING AND USE (CONTINUED)**

Electrolyte: Place neutralized slurry into sealed acid resistant containers and dispose of as hazardous waste, as applicable. Large water diluted spills, after neutralization and testing, should be managed in accordance with approved local, state, and federal requirements. Consult state environmental agency and/or federal EPA.

**Precautionary Labeling:**

POISON - CAUSES SEVERE BURNS  
DANGER - EXPLOSIVE GASES

CORROSIVE - CONTAINS SULFURIC ACID  
KEEP AWAY FROM CHILDREN

**VIII. CONTROL MEASURES****Engineering Controls and Work Practices:**

Store and handle in well-ventilated area. If mechanical ventilation is used, components must be acid-resistant. Handle batteries cautiously, do not tip to avoid spills. Make certain vent caps are on securely. If battery case is damaged, avoid bodily contact with internal components. Wear protective clothing, eye and face protection, when filling, charging, or handling batteries.

**Respiratory Protection:**

None required under normal conditions. When concentrations of sulfuric acid mist are known to exceed PEL, use NIOSH or MSHA-approved respiratory protection.

**Protective gloves:**

Rubber or plastic acid-resistant gloves with elbow-length gauntlet.

**Eye Protection:**

Chemical goggles or face shield.

**Other Protection:**

Acid-resistant apron. Under severe exposure or emergency conditions, wear acid-resistant clothing, gloves, and boots.

**Emergency Flushing:**

In areas where water and sulfuric acid solutions are handled in concentrations greater than 1%, emergency eyewash stations and showers should be provided, with unlimited water supply.

**IX. OTHER REGULATORY INFORMATION****NFPA Hazard Rating for sulfuric acid:**

|                     |   |   |
|---------------------|---|---|
| Flammability (Red)  | = | 0 |
| Health (Blue)       | = | 3 |
| Reactivity (Yellow) | = | 2 |

Sulfuric acid is water-reactive if concentrated.

**TRANSPORTATION:** Wet (filled with electrolyte) batteries are regulated by U.S. DOT as a hazardous material, as provided in 49 CFR 173.159

|                        |                                |
|------------------------|--------------------------------|
| Proper Shipping Name:  | Battery, wet, filled with acid |
| Hazard Class/Division: | 8                              |
| ID Number:             | UN2794                         |
| Packing Group:         | III                            |
| Label Required:        | Corrosive                      |

**RCRA:** Spent lead-acid batteries are not regulated as hazardous waste when recycled. Spilled sulfuric acid is a characteristic hazardous waste; EPA hazardous waste number D002 (corrosivity).

**CERCLA (Superfund) and EPCRA:**

- (a) Reportable Quantity (RQ) for spilled 100% sulfuric acid under CERCLA (Superfund) and EPCRA (Emergency Planning and Community Right to Know Act) is **1,000 lbs.** State and local reportable quantities for spilled sulfuric acid may vary.
- (b) Sulfuric acid is a listed "Extremely Hazardous Substance" under EPCRA, with a Threshold Planning Quantity (TPQ) of **1,000 lbs.**
- (c) EPCRA Section 302 notification is required if **1,000 lbs** or more of sulfuric acid is present at one site. An average automotive/commercial battery contains approximately 5 lbs of sulfuric acid. Contact your Exide representative for additional information.
- (d) EPCRA Section 312 Tier Two reporting is required for non-automotive batteries if sulfuric acid is present in quantities of **500 lbs** or more and/or if lead is present in quantities of **10,000 lbs** or more.

**IX. OTHER REGULATORY INFORMATION (CONTINUED)**

- (e) **Supplier Notification:** This product contains toxic chemicals that may be reportable under EPCRA Section 313 Toxic Chemical Release Inventory (Form R) requirements. For a manufacturing facility under SIC codes 20 through 39, the following information is provided to enable you to complete the required reports:

| <u>Toxic Chemical</u>                                                                            | <u>CAS Number</u> | <u>Approximate<br/>% by Weight</u> |
|--------------------------------------------------------------------------------------------------|-------------------|------------------------------------|
| Lead                                                                                             | 7439-92-1         | 54-62                              |
| Sulfuric Acid/Water Solution                                                                     | 7664-93-9         | 26-40                              |
| *Antimony                                                                                        | 7440-36-0         | 0.4                                |
| *Arsenic                                                                                         | 7440-38-2         | 0.01                               |
| *Not present in all battery types. Contact your Exide representative for additional information. |                   |                                    |

If you distribute this product to other manufacturers in SIC Codes 20 through 39, this information must be provided with the first shipment of each calendar year.

**Note:** The Section 313 supplier notification requirement does not apply to batteries that are "consumer products".

**CAA:**

Exide Technologies supports preventative actions concerning ozone depletion in the atmosphere due to emissions of CFC's and other ozone depleting chemicals (ODC's), defined by the USEPA as Class I substances. Pursuant to Section 611 of the Clean Air Act Amendments (CAAA) of 1990, finalized on January 19, 1993, Exide established a policy to eliminate the use of Class I ODC's prior to the May 15, 1993 deadline.

**TSCA:**

Ingredients in Exide's batteries are listed in the TSCA Registry as follows:

|                                                              | <u>CAS NO.</u> | <u>TSCA Status</u> |
|--------------------------------------------------------------|----------------|--------------------|
| Electrolyte: Sulfuric acid (H <sub>2</sub> SO <sub>4</sub> ) | 7664-93-9      | Listed             |
| Inorganic Lead Compound                                      |                |                    |
| Lead (Pb)                                                    | 7439-92-1      | Listed             |
| Lead Oxide (PbO)                                             | 1317-36-8      | Listed             |
| Lead Sulfate (PbSO <sub>4</sub> )                            | 7446-14-2      | Listed             |
| Antimony (Sb)                                                | 7440-36-0      | Listed             |
| Arsenic (As)                                                 | 7440-38-2      | Listed             |
| Calcium (Ca)                                                 | 7440-70-2      | Listed             |
| Tin (Sn)                                                     | 7440-31-5      | Listed             |

**CANADIAN REGULATIONS:**

All chemical substances in this product are listed on the CEPA DSL/NDSL or are exempt from list requirements.

**CALIFORNIA PROPOSITION 65:** "WARNING: This product contains lead, a chemical known to the State of California to cause cancer, or birth defects or other reproductive harm."

PREPARED BY: ENVIRONMENTAL, SAFETY AND HEALTH DEPARTMENT  
EXIDE TECHNOLOGIES  
13000 DEERFIELD PKWY., BLDG. 200  
MILTON, GA 30004

VENDEE AND THIRD PERSONS ASSUME THE RISK OF INJURY PROXIMATELY CAUSED BY THE MATERIAL IF REASONABLE SAFETY PROCEDURES ARE NOT FOLLOWED AS PROVIDED FOR IN THE DATA SHEET, AND VENDOR SHALL NOT BE LIABLE FOR INJURY TO VENDEE OR THIRD PERSONS PROXIMATELY CAUSED BY ABNORMAL USE OF THE MATERIAL EVEN IF REASONABLE PROCEDURES ARE FOLLOWED.

ALL PERSONS USING THIS PRODUCT, ALL PERSONS WORKING IN AN AREA WHERE THIS PRODUCT IS USED, AND ALL PERSONS HANDLING THIS PRODUCT SHOULD BE FAMILIAR WITH THE CONTENTS OF THIS DATA SHEET. THIS INFORMATION SHOULD BE EFFECTIVELY COMMUNICATED TO EMPLOYEES AND OTHERS WHO MIGHT COME IN CONTACT WITH THE PRODUCT.

WHILE THE INFORMATION ACCUMULATED AND SET FORTH HEREIN IS BELIEVED TO BE ACCURATE AS OF THE DATE HEREOF, EXIDE TECHNOLOGIES MAKES NO WARRANTY WITH RESPECT THERETO AND DISCLAIMS ALL LIABILITY FROM RELIANCE THEREON. RECIPIENTS ARE ADVISED TO CONFIRM IN ADVANCE OF NEED THAT THE INFORMATION IS CURRENT, APPLICABLE, AND SUITABLE FOR THEIR PARTICULAR CIRCUMSTANCES.

ANY PHOTOCOPY MUST BE OF THIS ENTIRE DOCUMENT

**From:** [Larry Eagan](#)  
**To:** [Eric Pastor](#)  
**Cc:** "[Love, Matt](#)"; [Roberta Russell](#); [Will Vienne](#)  
**Subject:** RE: Frisco Feed Material  
**Date:** Wednesday, June 05, 2013 12:41:14 PM

---

Eric, Broken automotive batteries were the main feed source for the secondary lead industry. The list looks fine for the Plant. The Reverb Furnace would have received the majority of the feed materials listed. Some of the items were generated in-house i.e. the reverb slag, which was the main source of feed for the Blast Furnace plus the industrial cells and some drosses. Most of the remelt items such as scrap lead: ingots, wheel weights, lead shot, expanded grid and punch-outs, cable strips and lead anodes would be recycled in the refining kettles, but could be fed to one of the furnaces also.

If you have any questions call me 214-215-5011. Larry

---

**From:** Eric Pastor [<mailto:eric.pastor@pbwllc.com>]  
**Sent:** Tuesday, June 04, 2013 6:14 PM  
**To:** Larry Eagan ([lgeagan@verizon.net](mailto:lgeagan@verizon.net))  
**Cc:** Love, Matt; Roberta Russell; Will Vienne  
**Subject:** Frisco Feed Material

Hi Larry –

Attached is a table listing the composition of Frisco feed materials in 2011. Could you look it over and let me know if this general composition is historically true for the Frisco operation – i.e., were scrap batteries pretty much always the primary feed material? If not, what was?

Thanks.

Eric Pastor  
Pastor, Behling & Wheeler, LLC  
2201 Double Creek Drive, Suite 4004  
Round Rock, Texas 78664  
512-671-3434

**APPENDIX 24**  
**SPLP DATA SUMMARY**

May 2014

Table A24-1  
**SPLP Data Summary (2014)**

Affected Property Assessment Report

| Analyte      |                      |              | Cadmium      | Lead        |
|--------------|----------------------|--------------|--------------|-------------|
| Units        |                      |              | mg/L         | mg/L        |
| Location ID  | Sample ID            | Date Sampled |              |             |
| 2013-AD-3    | 2013-AD-03 (0-0.5)   | 2014-01-09   | --           | 0.0790      |
| 2013-C2L-06  | 2013-C2L-06 (0-0.5)  | 2014-01-14   | --           | 0.0201      |
| 2013-CUFT-5B | 2013-CUFT-5B (0-0.5) | 2014-01-10   | --           | 0.101       |
| 2013-FWFS-5B | MW-33/2013-FWFS-5B   | 2014-01-10   | --           | < 0.00290 U |
| 2013-MB-5    | 2013-MB-5 (0.5-5)    | 2014-01-08   | < 0.000350 U | --          |
| 2013-NT-02   | 2013-NT-02 (0-0.5)   | 2014-01-10   | --           | 0.0376      |
| 2013-SDA-3B  | 2013-SDA-3B (0-0.5)  | 2014-01-09   | --           | 0.114       |
| SCC-5B       | SCC-5B (0-0.5)       | 2014-01-10   | --           | 0.209       |

## Notes:

1. "--" - not analyzed.
2. < - analyte not detected above SDL; U - not detected.

**Table A24-2**  
**SPLP Data Summary**

| Sample ID         | Sample Date | Sample Depth (feet bgs) | SPLP Results   |             |
|-------------------|-------------|-------------------------|----------------|-------------|
|                   |             |                         | Cadmium (mg/L) | Lead (mg/L) |
| 2012-BSA-3A(0-2') | 3/23/2012   | 0-2                     | 0.0125         | --          |
| 2012-BSA-4a(0-1') | 3/29/2012   | 0-1                     | 0.0018 U       | 0.354       |
| 2012-BSA-4c(0-1') | 3/29/2012   | 0-1                     | 0.0041 U       | 0.706       |
| 2012-BSA-4d(0-1') | 3/29/2012   | 0-1                     | 0.0068         | 1.54        |

Notes:

1. "--" - not analyzed.
1. Data Qualifiers (see Section 3.5): U - blank contamination.

**APPENDIX 25**  
**SIR AND APAR SAMPLE COORDINATES**

May 2014

Table A25-1

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID                  | Northing | Easting |
|------------------------------|----------|---------|
| <b>Soil Sample Locations</b> |          |         |
| 2012-BSA-1                   | 7102274  | 2480624 |
| 2012-BSA-1A                  | 7102276  | 2480629 |
| 2012-BSA-2                   | 7102274  | 2480735 |
| 2012-BSA-3                   | 7102224  | 2480672 |
| 2012-BSA-3A                  | 7102220  | 2480676 |
| 2012-BSA-4                   | 7102173  | 2480639 |
| 2012-BSA-5                   | 7102165  | 2480739 |
| 2012-BY-1                    | 7102377  | 2479501 |
| 2012-BY-2                    | 7102343  | 2479613 |
| 2012-BY-3                    | 7102239  | 2479660 |
| 2012-BY-4                    | 7102231  | 2479579 |
| 2012-BY-5                    | 7102282  | 2479516 |
| 2012-CUFT-1                  | 7101786  | 2479394 |
| 2012-CUFT-2                  | 7101783  | 2479434 |
| 2012-FWCS-1                  | 7102032  | 2479676 |
| 2012-FWCS-11                 | 7102055  | 2479651 |
| 2012-FWCS-12                 | 7102060  | 2479678 |
| 2012-FWCS-2                  | 7101912  | 2479827 |
| 2012-FWCS-3                  | 7101904  | 2479837 |
| 2012-FWCS-4                  | 7101886  | 2479859 |
| 2012-FWCS-5                  | 7101863  | 2479891 |
| 2012-FWCS-6                  | 7101824  | 2479945 |
| 2012-FWCS-7                  | 7101805  | 2479966 |
| 2012-FWCS-8                  | 7101746  | 2480046 |
| 2012-FWCS-9                  | 7101706  | 2480100 |
| 2012-FWFS-1                  | 7101960  | 2479788 |
| 2012-FWFS-2                  | 7101918  | 2479841 |
| 2012-FWFS-3                  | 7101888  | 2479880 |
| 2012-FWFS-4                  | 7101873  | 2479898 |
| 2012-FWFS-5                  | 7101843  | 2479937 |
| 2012-FWFS-6                  | 7101812  | 2479976 |
| 2012-FWFS-7                  | 7101780  | 2480015 |
| 2012-FWFS-7A                 | 7101767  | 2480012 |
| 2012-FWFS-7B                 | 7101757  | 2480012 |
| 2012-FWFS-8                  | 7101749  | 2480054 |
| 2012-FWFS-9                  | 7101720  | 2480095 |
| 2012-NDA-1                   | 7102386  | 2480119 |
| 2012-NDA-2                   | 7102390  | 2480412 |
| 2012-NDA-3                   | 7102444  | 2480662 |
| 2012-NDA-4                   | 7102396  | 2480119 |
| 2012-NDA-5                   | 7102460  | 2480666 |
| 2012-NDA-6                   | 7102503  | 2480666 |

May 2014

Table A25-1

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID      | Northing | Easting |
|------------------|----------|---------|
| 2012-RMSA-1      | 7101962  | 2480182 |
| 2012/2013-RMSA-2 | 7101817  | 2480247 |
| 2012-RMSA-3      | 7101783  | 2480191 |
| 2012-RMSA-4      | 7101861  | 2480123 |
| 2012-SDA-1       | 7101559  | 2480089 |
| 2012-SDA-2       | 7101558  | 2480185 |
| 2012-SDA-3       | 7101553  | 2480292 |
| 2012-SDA-4       | 7101174  | 2479971 |
| 2012-SDA-5       | 7101170  | 2480098 |
| 2012-SL-1        | 7102344  | 2479384 |
| 2012-SL-2        | 7102486  | 2479521 |
| 2012-SL-3        | 7102515  | 2479698 |
| 2013-AD-1        | 7101896  | 2480808 |
| 2013-AD-2        | 7101914  | 2480990 |
| 2013-AD-2A       | 7101931  | 2481017 |
| 2013-B4R-A       | 7101415  | 2479943 |
| 2013-BB-1        | 7102007  | 2480117 |
| 2013-BSA-6       | 7102201  | 2480652 |
| 2013-BSA-7       | 7102251  | 2480716 |
| 2013-BSB-1       | 7102047  | 2479712 |
| 2013-BSB-2       | 7102035  | 2479771 |
| 2013-BSB-3       | 7102030  | 2479798 |
| 2013-BSB-4       | 7102020  | 2479815 |
| 2013-BSB-5       | 7102021  | 2479781 |
| 2013-BSB-6       | 7102031  | 2479850 |
| 2013-BSB-7       | 7102021  | 2479830 |
| 2013-BSB-8       | 7102045  | 2479812 |
| 2013-BSB-9       | 7102065  | 2479812 |
| 2013-BSB-10      | 7102050  | 2479884 |
| 2013-CUFT-10     | 7101931  | 2478954 |
| 2013-CUFT-3      | 7101738  | 2479345 |
| 2013-CUFT-4      | 7101889  | 2479303 |
| 2013-CUFT-5      | 7101906  | 2479178 |
| 2013-CUFT-6      | 7101911  | 2479083 |
| 2013-CUFT-7      | 7101923  | 2478975 |
| 2013-CUFT-7A     | 7101908  | 2478965 |
| 2013-CUFT-8      | 7101684  | 2479346 |
| 2013-CUFT-9      | 7101762  | 2479324 |
| 2013-FOP-1       | 7101872  | 2480549 |
| 2012-FWCS-1A     | 7102026  | 2479671 |
| 2013-FWCS-1B     | 7102016  | 2479669 |
| 2013-FWFS-1A     | 7101951  | 2479776 |
| 2013-MB-1        | 7101769  | 2480379 |

May 2014

Table A25-1

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID  | Northing | Easting |
|--------------|----------|---------|
| 2013-MB-2    | 7101790  | 2480309 |
| 2013-MW10-1  | 7101995  | 2480989 |
| 2013-MW10-2  | 7101953  | 2480966 |
| 2013-MW10-3  | 7101989  | 2480897 |
| 2013-MW-17A  | 7102073  | 2479607 |
| 2013-RMSA-5  | 7101857  | 2480261 |
| 2013-RMSA-6  | 7101796  | 2480248 |
| 2013-RMSA-7  | 7101813  | 2480272 |
| 2013-RMSB-1  | 7101910  | 2480143 |
| 2013-RMSB-2  | 7101911  | 2480173 |
| 2013-RMSB-3  | 7101921  | 2480185 |
| 2013-RMSB-4  | 7101919  | 2480206 |
| 2013-RMSB-5  | 7101878  | 2480144 |
| 2013-RMSB-6  | 7101880  | 2480175 |
| 2013-RMSB-7  | 7101881  | 2480206 |
| 2013-RMSB-8  | 7101841  | 2480147 |
| 2013-RMSB-9  | 7101851  | 2480176 |
| 2013-RMSB-10 | 7101844  | 2480209 |
| 2013-RO-1    | 7102104  | 2479578 |
| 2013-RO-2    | 7102126  | 2479562 |
| 2013-RO-3    | 7102105  | 2479557 |
| 2013-RRS-3A  | 7102074  | 2480071 |
| 2013-RRS-4A  | 7102061  | 2480184 |
| 2013-SDA-3A  | 7101577  | 2480331 |
| 2013-SDA-4A  | 7101588  | 2480228 |
| 2013-SL-4    | 7102264  | 2479415 |
| 2013-STB-1   | 7101857  | 2480007 |
| 2013-STB-2   | 7101810  | 2480060 |
| 2013-STB-3   | 7101843  | 2480095 |
| 2013-STB-4   | 7101764  | 2480125 |
| 2013-STB-5   | 7101810  | 2480039 |
| 2013-STB-6   | 7101799  | 2480031 |
| 2013-STB-7   | 7101819  | 2480034 |
| 2013-STB-8   | 7101853  | 2479990 |
| 2013-STB-9   | 7101812  | 2479996 |
| 2013-STB-10  | 7101832  | 2479972 |
| 2013-STB-11  | 7101768  | 2480095 |
| 2013-STB-12  | 7101781  | 2480016 |
| 2013-TS-1    | 7102097  | 2480985 |
| 2013-TS-2    | 7102253  | 2480977 |
| 2013-WMU14-1 | 7101992  | 2479881 |
| 2013-WMU14-2 | 7101826  | 2480109 |
| 2013-WMU14-3 | 7102021  | 2480631 |
| 2013-WMU16-1 | 7101886  | 2480415 |
| 2013-WMU17-1 | 7102328  | 2479645 |

May 2014

Table A25-1

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID  | Northing | Easting |
|--------------|----------|---------|
| 2013-WMU17-2 | 7102359  | 2479608 |
| 2013-WMU6-1  | 7101955  | 2479994 |
| BS2/BS-2     | 7101513  | 2480178 |
| BS3/BS-3     | 7101491  | 2480215 |
| BS5/BS-5     | 7101472  | 2480114 |
| D-11         | 7102885  | 2480148 |
| D-12         | 7102903  | 2480324 |
| D-13         | 7102912  | 2480533 |
| D-14         | 7102922  | 2480738 |
| D-15         | 7102934  | 2480891 |
| E-11         | 7102766  | 2480144 |
| E-11A        | 7102808  | 2480069 |
| E-11B        | 7102810  | 2480025 |
| E-12         | 7102779  | 2480324 |
| E-13         | 7102785  | 2480532 |
| E-14         | 7102785  | 2480740 |
| E-15         | 7102789  | 2480893 |
| E-15A        | 7102787  | 2480940 |
| ECO-1        | 7101378  | 2481004 |
| ECO-2        | 7101283  | 2481006 |
| ECO-3        | 7101296  | 2480817 |
| ECO-4        | 7101170  | 2480822 |
| ECO-5        | 7101456  | 2480753 |
| ECO-6        | 7101325  | 2480601 |
| ECO-7        | 7101179  | 2480616 |
| ECO-7A       | 7101171  | 2480616 |
| ECO-7B       | 7101169  | 2480617 |
| ECO-8        | 7101519  | 2480460 |
| ECO-9        | 7101336  | 2480436 |
| ECO-10       | 7101188  | 2480411 |
| ECO-11       | 7102588  | 2480248 |
| ECO-12       | 7102509  | 2480907 |
| F-4          | 7102498  | 2478704 |
| F-5          | 7102506  | 2478851 |
| G-4          | 7102306  | 2478654 |
| G4-2         | 7102306  | 2478726 |
| G-5          | 7102314  | 2478858 |
| G-6          | 7102321  | 2479003 |
| H-3          | 7102091  | 2478502 |
| H-4          | 7102117  | 2478642 |
| H4-2         | 7102190  | 2478643 |
| H-5          | 7102108  | 2478861 |

May 2014

Table A25-1

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID                                        | Northing | Easting |
|----------------------------------------------------|----------|---------|
| H5-2                                               | 7102190  | 2478829 |
| SB-VS-1                                            | 7101204  | 2480012 |
| SB-VS-2                                            | 7101204  | 2480038 |
| SCC-1                                              | 7101615  | 2480808 |
| SCC-2                                              | 7101587  | 2480643 |
| SCC-3                                              | 7101667  | 2480461 |
| SCC-3A                                             | 7101642  | 2480461 |
| SCC-4                                              | 7101635  | 2480261 |
| SCC-5                                              | 7101681  | 2480057 |
| SCC-6                                              | 7101806  | 2479940 |
| SCC-7                                              | 7101888  | 2479772 |
| SCC-8                                              | 7102032  | 2479666 |
| SCC-9                                              | 7102060  | 2479550 |
| SCC-10                                             | 7102157  | 2479519 |
| SCC-10A                                            | 7102143  | 2479513 |
| SCC-11                                             | 7102320  | 2479302 |
| SCC-11A                                            | 7102284  | 2479298 |
| SCC-12                                             | 7102415  | 2479175 |
| SCC-13                                             | 7102540  | 2479020 |
| SCC-14                                             | 7102630  | 2478907 |
| SCC-15                                             | 7102753  | 2478750 |
| SRB-VS-1                                           | 7101345  | 2479944 |
| SRB-VS-2                                           | 7101305  | 2479958 |
| SRB-VS-3                                           | 7101268  | 2479965 |
| SRB-VS-4                                           | 7101231  | 2479973 |
| SRB-VS-5                                           | 7101342  | 2479922 |
| SRB-VS-6                                           | 7101302  | 2479921 |
| SRB-VS-7                                           | 7101265  | 2479928 |
| SRB-VS-8                                           | 7101228  | 2479938 |
| SRB-VS-9                                           | 7101362  | 2479938 |
| SRB-VS-9A                                          | 7101374  | 2479937 |
| SRB-VS-9B                                          | 7101360  | 2479915 |
| SRB-VS-9C                                          | 7101389  | 2479912 |
| SRB-VS-10                                          | 7101301  | 2479913 |
| SRB-VS-11                                          | 7101212  | 2479934 |
| <b>Sediment and Surface Water Sample Locations</b> |          |         |
| 2012-SED/SW-1                                      | 7102703  | 2478733 |
| 2012-SED/SW-2                                      | 7102611  | 2478876 |
| 2012-SED/SW-3                                      | 7102438  | 2479073 |

May 2014

**Table A25-1**

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| <b>Location ID</b>   | <b>Northing</b> | <b>Easting</b> |
|----------------------|-----------------|----------------|
| 2012-SED/SW-4        | 7102268         | 2479293        |
| 2012-SED/SW-5        | 7102120         | 2479505        |
| 2012-SED/SW-6        | 7101898         | 2479807        |
| 2012-SED/SW-7        | 7101823         | 2479899        |
| 2012-SED/SW-8        | 7101716         | 2480025        |
| 2012-SED/SW-9        | 7101656         | 2480206        |
| 2012-SED/SW-10       | 7101633         | 2480422        |
| 2012-SED/SW-11       | 7101623         | 2480599        |
| 2012-SED/SW-12       | 7101570         | 2480832        |
| 2012-SED/SW-13       | 7101526         | 2481023        |
| 2012-SED/SW-14       | 7101533         | 2481101        |
| 2012-SED/SW-15       | 7101496         | 2481175        |
| 2012-SED-16/SW-NT-1  | 7102485         | 2479310        |
| 2012-SED-17/SW-NT-2  | 7102524         | 2479437        |
| 2012-SED-18/SW-NT-3  | 7102552         | 2479564        |
| 2012-SED-19/SW-NT-4  | 7102605         | 2479764        |
| 2012-SED-20/SW-NT-5  | 7102644         | 2479998        |
| 2012-SED-21/SW-NT-6  | 7102681         | 2480214        |
| 2012-SED-22/SW-NT-7  | 7102676         | 2480365        |
| 2012-SED-23/SW-NT-8  | 7102653         | 2480575        |
| 2012-SED-24/SW-NT-9  | 7102611         | 2480779        |
| 2012-SED-25/SW-NT-10 | 7102634         | 2480926        |

Notes:

1. Coordinate System: Texas State Plane North Central Zone, NAD 83, units in feet.

May 2014

Table A25-2

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID                  | Northing | Easting |
|------------------------------|----------|---------|
| <b>Soil Sample Locations</b> |          |         |
| 2013-AD-1A                   | 7101873  | 2480792 |
| 2013-AD-3                    | 7101762  | 2480927 |
| 2013-AD-4                    | 7101685  | 2480811 |
| 2013-AD-5                    | 7101826  | 2480595 |
| 2013-BSA-2A                  | 7102283  | 2480731 |
| 2013-BSB-8A                  | 7102056  | 2479815 |
| 2013-C2L-01                  | 7103855  | 2480668 |
| 2013-C2L-02                  | 7103459  | 2480901 |
| 2013-C2L-03                  | 7103191  | 2480793 |
| 2013-C2L-04                  | 7103041  | 2480728 |
| 2013-C2L-05                  | 7103082  | 2480098 |
| 2013-C2L-06                  | 7103315  | 2480135 |
| 2013-C2L-07                  | 7103532  | 2480172 |
| 2013-C2L-08                  | 7103900  | 2480452 |
| 2013-C2L-09                  | 7103008  | 2480517 |
| 2013-C2L-10                  | 7103062  | 2480295 |
| 2013-C2L-C01                 | 7103200  | 2480194 |
| 2013-C2L-C02                 | 7103142  | 2480386 |
| 2013-C2L-C03                 | 7103087  | 2480579 |
| 2013-C2L-C04                 | 7103369  | 2480255 |
| 2013-C2L-C05                 | 7103315  | 2480437 |
| 2013-C2L-C06                 | 7103260  | 2480631 |
| 2013-CUFT-10A                | 7101951  | 2478954 |
| 2013-CUFT-10B                | 7101932  | 2478939 |
| 2013-CUFT-10C                | 7101916  | 2478954 |
| 2013-CUFT-10D                | 7101931  | 2478954 |
| 2013-CUFT-11                 | 7101777  | 2479386 |
| 2013-CUFT-14                 | 7101786  | 2479526 |
| 2013-CUFT-5A                 | 7101932  | 2479179 |
| 2013-CUFT-5B                 | 7101906  | 2479193 |
| 2013-CUFT-5C                 | 7101888  | 2479179 |
| 2013-CUFT-5D                 | 7101906  | 2479178 |
| 2013-CUFT-6A                 | 7101926  | 2479083 |
| 2013-CUFT-6B                 | 7101896  | 2479083 |
| 2013-CUFT-6C                 | 7101911  | 2479083 |
| 2013-CUFT-7B                 | 7101932  | 2478969 |
| 2013-FFTA-01                 | 7102397  | 2480828 |
| 2013-FFTA-02                 | 7102378  | 2480781 |
| 2013-FFTA-03                 | 7102425  | 2480753 |
| 2013-FFTA-03                 | 7102425  | 2480753 |
| 2013-FOP-1A                  | 7101866  | 2480555 |
| 2013-FWCS-12A                | 7102067  | 2479682 |
| 2013-FWFS-5A                 | 7101833  | 2479918 |
| 2013-FWFS-5B                 | 7101872  | 2480021 |
| 2013-MB-3                    | 7101808  | 2480461 |
| 2013-MB-4                    | 7101869  | 2480347 |
| 2013-MB-5                    | 7101720  | 2480355 |

May 2014

Table A25-2

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| <b>Location ID</b> | <b>Northing</b> | <b>Easting</b> |
|--------------------|-----------------|----------------|
| 2013-MW-17B        | 7102077         | 2479603        |
| 2013-NDA-1A        | 7102386         | 2480106        |
| 2013-NDA-C01       | 7102331         | 2480012        |
| 2013-NDA-C02       | 7102332         | 2480098        |
| 2013-NDA-C03       | 7102335         | 2480196        |
| 2013-NDA-C04       | 7102337         | 2480288        |
| 2013-NDA-C05       | 7102343         | 2480381        |
| 2013-NDA-C06       | 7102349         | 2480475        |
| 2013-NDA-C07       | 7102354         | 2480570        |
| 2013-NDA-C08       | 7102258         | 2480573        |
| 2013-NDA-C09       | 7102256         | 2480484        |
| 2013-NDA-C10       | 7102255         | 2480392        |
| 2013-NDA-C11       | 7102244         | 2480298        |
| 2013-NDA-C12       | 7102252         | 2480193        |
| 2013-NDA-C13       | 7102246         | 2480094        |
| 2013-NDA-C14       | 7102244         | 2480006        |
| 2013-NDA-C15       | 7102241         | 2479918        |
| 2013-NDA-C16       | 7102237         | 2479823        |
| 2013-NDA-C17       | 7102186         | 2479729        |
| 2013-NDA-C18       | 7102178         | 2479813        |
| 2013-NDA-C19       | 7102167         | 2479911        |
| 2013-NDA-C20       | 7102165         | 2480009        |
| 2013-NDA-C21       | 7102159         | 2480099        |
| 2013-NDA-C22       | 7102156         | 2480184        |
| 2013-NDA-C23       | 7102163         | 2480295        |
| 2013-NDA-C24       | 7102162         | 2480383        |
| 2013-NDA-C25       | 7102160         | 2480582        |
| 2013-NT-01         | 7102698         | 2480314        |
| 2013-NT-02         | 7102697         | 2480580        |
| 2013-RMSB-5A       | 7101885         | 2480146        |
| 2013-RRS-4A-A      | 7102058         | 2480186        |
| 2013-SDA-3B        | 7101606         | 2480328        |
| 2013-SDA-4B        | 7101638         | 2480213        |
| 2013-SDA-C01       | 7101429         | 2480080        |
| 2013-SDA-C02       | 7101339         | 2479968        |
| 2013-SDA-C03       | 7101239         | 2479989        |
| 2013-SDA-C04       | 7101328         | 2480068        |
| 2013-SDA-C05       | 7101319         | 2480177        |
| 2013-SDA-C06       | 7101309         | 2480289        |
| 2013-SL-C01        | 7102204         | 2479607        |
| 2013-SL-C02        | 7102284         | 2479441        |
| 2013-SL-C03        | 7102291         | 2479507        |
| 2013-SL-C04        | 7102302         | 2479601        |
| 2013-SL-C05        | 7102312         | 2479697        |
| 2013-SL-C06        | 7102323         | 2479791        |
| 2013-SL-C07        | 7102378         | 2479383        |
| 2013-SL-C08        | 7102385         | 2479501        |
| 2013-SL-C09        | 7102401         | 2479591        |

May 2014

Table A25-2

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID    | Northing | Easting |
|----------------|----------|---------|
| 2013-SL-C10    | 7102415  | 2479684 |
| 2013-SL-C11    | 7102433  | 2479775 |
| 2013-SL-C12    | 7102448  | 2479862 |
| 2013-SL-C13    | 7102470  | 2479962 |
| 2013-SL-C14    | 7102504  | 2479765 |
| 2013-SL-C15    | 7102535  | 2479858 |
| 2013-SL-C16    | 7102547  | 2479954 |
| 2013-STB-4A    | 7101776  | 2480135 |
| 2013-WMU14-1A  | 7101992  | 2479883 |
| 2014-AD-3A     | 7101762  | 2480926 |
| 2014-AD-6      | 7101642  | 2480942 |
| 2014-C2L-06A   | 7103401  | 2480137 |
| 2014-C2L-06B   | 7103303  | 2480058 |
| 2014-C2L-06C   | 7103214  | 2480124 |
| 2014-C2L-C01A  | 7103242  | 2480193 |
| 2014-C2L-C01B  | 7103200  | 2480225 |
| 2014-C2L-C01C  | 7103137  | 2480206 |
| 2014-CUFT-15   | 7101943  | 2478859 |
| 2014-CUFT-16   | 7101951  | 2478764 |
| 2014-CUFT-17   | 7101984  | 2478621 |
| 2014-CUFT-18   | 7101940  | 2479079 |
| 2014-CUFT-5B-A | 7101909  | 2479204 |
| 2014-FFTA-04   | 7102336  | 2480847 |
| 2014-FFTA-05   | 7102439  | 2480779 |
| 2014-FFTA-06   | 7102418  | 2480618 |
| 2014-FFTA-07   | 7102435  | 2480573 |
| 2014-FFTA-08   | 7102462  | 2480620 |
| 2014-NDA-7     | 7102403  | 2480551 |
| 2014-NDA-8     | 7102410  | 2480359 |
| 2014-NDA-9     | 7102398  | 2480108 |
| 2014-NT-3      | 7102635  | 2479788 |
| 2014-NT-4      | 7102580  | 2479519 |
| 2014-SDA-6     | 7101659  | 2479999 |
| 2014-SDA-7     | 7101210  | 2480015 |
| 2014-SL-5      | 7102602  | 2479957 |
| 2014-SL-6      | 7102477  | 2479401 |
| 2014-SL-7      | 7102412  | 2479287 |
| 2014-TS-3      | 7102166  | 2480979 |
| B3RA           | 7101497  | 2479989 |
| D-11A          | 7102905  | 2480145 |
| D-11B          | 7102980  | 2480129 |
| D-12A          | 7102914  | 2480333 |
| D-13A          | 7102922  | 2480530 |
| E-11C          | 7102811  | 2480050 |
| E-11C-A        | 7102807  | 2480052 |
| E-11D          | 7102709  | 2480121 |
| E-11E          | 7102720  | 2480119 |
| E-12A          | 7102758  | 2480294 |

May 2014

Table A25-2

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID                                        | Northing | Easting |
|----------------------------------------------------|----------|---------|
| E-13A                                              | 7102771  | 2480548 |
| E-14A                                              | 7102778  | 2480731 |
| ECO-10A                                            | 7101182  | 2480399 |
| ECO-1A                                             | 7101375  | 2481023 |
| ECO-2A                                             | 7101290  | 2481023 |
| ECO-4A                                             | 7101154  | 2480847 |
| ECO-4B                                             | 7101151  | 2480940 |
| ECO-7C                                             | 7101203  | 2480611 |
| ECO-7D                                             | 7101170  | 2480614 |
| ECO-8A                                             | 7101537  | 2480457 |
| ECO-8B                                             | 7101601  | 2480466 |
| F-5A                                               | 7102507  | 2478846 |
| F-5B                                               | 7102527  | 2478845 |
| F-5C                                               | 7102506  | 2478867 |
| F-5D                                               | 7102487  | 2478845 |
| F-5E                                               | 7102507  | 2478825 |
| MW-27A                                             | 7101688  | 2480187 |
| MW-27B                                             | 7101682  | 2480227 |
| MW-27C                                             | 7101680  | 2480293 |
| MW-27D                                             | 7101691  | 2480338 |
| MW-27E                                             | 7101667  | 2480260 |
| MW-29A                                             | 7101747  | 2480032 |
| MW-30A                                             | 7102080  | 2480016 |
| MW-35                                              | 7101736  | 2480191 |
| MW-36                                              | 7101815  | 2480274 |
| MW-41                                              | 7102693  | 2480074 |
| MW-42                                              | 7102696  | 2480712 |
| MW-43                                              | 7102422  | 2480782 |
| MW-44                                              | 7101660  | 2480550 |
| MW-45                                              | 7103915  | 2480303 |
| SCC-10B                                            | 7102140  | 2479514 |
| SCC-5A                                             | 7101692  | 2480025 |
| SCC-5B                                             | 7101661  | 2480068 |
| SRB-VS-11A                                         | 7101205  | 2479919 |
| SRB-VS-11B                                         | 7101204  | 2479918 |
| SRB-VS-9E                                          | 7101364  | 2479894 |
| <b>Sediment and Surface Water Sample Locations</b> |          |         |
| 2014-SED-001                                       | 7094272  | 2469837 |
| 2014-SED-002                                       | 7094341  | 2470034 |
| 2014-SED-003                                       | 7094406  | 2470197 |
| 2014-SED-004                                       | 7094388  | 2470469 |
| 2014-SED-005                                       | 7094626  | 2470501 |
| 2014-SED-006                                       | 7094599  | 2470929 |
| 2014-SED-007                                       | 7094816  | 2471058 |
| 2014-SED-008                                       | 7094981  | 2470996 |
| 2014-SED-009                                       | 7095244  | 2470959 |
| 2014-SED-010                                       | 7095333  | 2471402 |
| 2014-SED-011                                       | 7095376  | 2471620 |

May 2014

Table A25-2

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID  | Northing | Easting |
|--------------|----------|---------|
| 2014-SED-012 | 7095458  | 2471848 |
| 2014-SED-013 | 7095512  | 2472092 |
| 2014-SED-014 | 7102921  | 2477121 |
| 2014-SED-015 | 7102713  | 2477774 |
| 2014-SED-016 | 7102573  | 2478098 |
| 2014-SED-017 | 7102643  | 2478190 |
| 2014-SED-018 | 7102744  | 2478446 |
| 2014-SED-019 | 7099687  | 2475555 |
| 2014-SED-020 | 7100378  | 2475633 |
| 2014-SED-021 | 7100827  | 2475202 |
| 2014-SED-022 | 7101161  | 2475484 |
| 2014-SED-023 | 7101930  | 2475557 |
| 2014-SED-024 | 7102142  | 2475875 |
| 2014-SED-025 | 7102460  | 2476418 |
| 2014-SED-026 | 7101538  | 2481113 |
| 2014-SED-027 | 7101510  | 2481179 |
| 2014-SED-028 | 7101509  | 2481276 |
| 2014-SED-029 | 7101464  | 2481348 |
| 2014-SED-030 | 7101396  | 2481497 |
| 2014-SED-031 | 7101422  | 2481635 |
| 2014-SED-032 | 7101386  | 2481701 |
| 2014-SED-033 | 7101380  | 2481872 |
| 2014-SED-034 | 7101319  | 2481962 |
| 2014-SED-035 | 7101086  | 2481993 |
| 2014-SED-036 | 7095636  | 2472938 |
| 2014-SED-037 | 7095691  | 2472893 |
| 2014-SED-038 | 7096271  | 2472678 |
| 2014-SED-039 | 7096895  | 2472966 |
| 2014-SED-040 | 7096832  | 2473273 |
| 2014-SED-041 | 7097178  | 2473274 |
| 2014-SED-042 | 7097608  | 2473069 |
| 2014-SED-043 | 7098004  | 2473321 |
| 2014-SED-044 | 7098004  | 2473575 |
| 2014-SED-045 | 7097650  | 2474067 |
| 2014-SED-046 | 7097962  | 2473985 |
| 2014-SED-047 | 7094457  | 2469692 |
| 2014-SED-048 | 7098955  | 2474796 |
| 2014-SED-049 | 7099300  | 2475300 |
| 2014-SED-050 | 7091118  | 2462190 |
| 2014-SED-051 | 7091778  | 2462666 |
| 2014-SED-052 | 7092026  | 2463392 |
| 2014-SED-053 | 7091875  | 2463748 |
| 2014-SED-054 | 7091982  | 2464347 |
| 2014-SED-055 | 7092012  | 2464874 |
| 2014-SED-056 | 7091865  | 2465881 |
| 2014-SED-057 | 7092230  | 2466095 |
| 2014-SED-058 | 7092759  | 2466988 |
| 2014-SED-059 | 7092820  | 2467759 |

May 2014

Table A25-2

**Coordinate Data Summary**  
**SIR and APAR Phase I Soil Sample and Surface Water/Sediment Sample Locations**

| Location ID  | Northing | Easting |
|--------------|----------|---------|
| 2014-SED-060 | 7092788  | 2468312 |
| 2014-SED-061 | 7093301  | 2468570 |
| 2014-SED-062 | 7093738  | 2468733 |
| 2014-SED-063 | 7093577  | 2468996 |
| 2014-SW-001  | 7094816  | 2471058 |
| 2014-SW-002  | 7101538  | 2481113 |
| 2014-SW-003  | 7102573  | 2478098 |
| 2014-SW-004  | 7102643  | 2478190 |
| 2014-SW-005  | 7102744  | 2478446 |
| 2014-SW-006  | 7099687  | 2475555 |
| 2014-SW-007  | 7101510  | 2481179 |
| 2014-SW-008  | 7101509  | 2481276 |
| 2014-SW-009  | 7101464  | 2481348 |
| 2014-SW-010  | 7101396  | 2481497 |
| 2014-SW-011  | 7101422  | 2481635 |
| 2014-SW-012  | 7101386  | 2481701 |
| 2014-SW-013  | 7101380  | 2481872 |
| 2014-SW-014  | 7101319  | 2481962 |
| 2014-SW-015  | 7101086  | 2481993 |
| 2014-SW-016  | 7101554  | 2481002 |
| 2014-SW-017  | 7101900  | 2479818 |
| 2014-SW-018  | 7102140  | 2479505 |
| 2014-SW-019  | 7102261  | 2479330 |
| 2014-SW-020  | 7102412  | 2479117 |
| 2014-SW-021  | 7102731  | 2478732 |
| 2014-SW-022  | 7095691  | 2472893 |
| 2014-SW-023  | 7097608  | 2473069 |
| 2014-SW-024  | 7094457  | 2469692 |
| 2014-SW-025  | 7099300  | 2475300 |
| 2014-SW-026  | 7091778  | 2462666 |
| 2014-SW-027  | 7092026  | 2463392 |
| 2014-SW-028  | 7092230  | 2466095 |
| 2014-SW-029  | 7092788  | 2468312 |

**Notes:**

1. Coordinate System: Texas State Plane North Central Zone, NAD 83, units in feet.